

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305470609 Via Fax : Email
Date : 27 05 21 Your Insured : SLB8438 R
Time of Fax : _____ Date of Acc : 25 05 21

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

C 3361C

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ <u>Lim Tien Siong</u>	<u>Tel: 6214 8398 or HP: 9635 8546</u>
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **limts@cdege.com.sg**
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

DATE: 27.05.2021

3P INSURANCE: AIG ASIA

MODEL: HYUNDAI IONIQ

SURVEYOR: NA

VEH NO.: SHC3361C

MVA: LIM T S

-	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$459.40
	Rear Bumper Reinforcement	1		\$394.80
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20
	Rear Bumper Centre Moulding Assy	1		\$451.25
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00
	Rear Bumper Cover Clips	10	\$2.20	\$22.00
	Rear Bumper Tow Cover	1		\$98.80
	Rear Bumper Fog Lamp	1		\$201.50
	Boot Lid	1		\$2,480.40
	Emblem-Hybrid	1		\$24.30
	Emblem-Ioniq	1		\$31.30
	SPARE PARTS SUB TOTAL			\$4,594.95
	LESS 20%			\$918.99
	DISCOUNTED SPARE PARTS TOTAL			\$3,675.96
	Boot Lid ComfortDelGro & 65521111 Stickers	1		\$70.00
	Boot Lid Comfort Apps Sticker	1		\$40.00
	Rear Bumper Reverse Sensor	1		\$180.00
	Rear Windscreen Glasses Sealant	2	\$46.00	\$92.00
	Rear No.Plate W/Trim Cover	1		\$55.00
	NETT TOTAL			\$437.00
	SPARE PARTS & NETT TOTAL			\$4,112.96
	Panel Beating			\$800.00
	Spray Painting			\$600.00
	R/I Reverse Sensor			\$120.00
	R/I Both Rear Windscreen Glasses			\$200.00
	Check All Lightings/Wirings			\$40.00
	LABOUR TOTAL			\$1,760.00
	ESTIMATE TOTAL			\$5,872.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/05/2021 19:15 (SGT)
Date of Accident	25/05/2021 11:58 (SGT)
Exact Location of Accident	HarbourFront Walk & Telok Blangah Rd, Singapore
Additional Location Information	
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC3361C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-81888653
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	

DRIVER

Name of Driver	YONG MENG KOK
NRIC No	SXXXX927F

Date Of Birth	26/02/1968
Occupation	Outdoor
Date Of Driving Pass	20/11/1996
Driving experience	24 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81888653
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 676 CHOA CHU KANG CRESCENT#07-457
Address complement	-
Postcode	680676
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

25/5/2021 11:58AM I WAS STATIONARY AT THE SLIP ROAD TO ENSURE MAIN ROAD CLEAR FROM TRAFFIC. SUDDENLY VEHICLE B FROM MY BEHIND UNABLE TO STOP IN TIME AND HIT ONTO MY TAXI REAR PORTION. FROM THE IMPACT I FEELING UNWELL AND WILL SEEK MEDICAL CHECK-UP..

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB8438R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	UNKNOWN

Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	YONG MENG KOK
Address	BLK 676 CHOA CHU KANG CRESCENT #07-457
Address Complement	-
Post Code	680676
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SHC3361C
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel *Dol*

25/5/21

Sketch Plan

Describe Circumstances of the Accident

25/5/2021 11:58am I was stationary at the slip road to ensure main road clear from traffic. Suddenly vehicle B from my behind unable to stop in time and hit onto my taxi rear portion. From the impact I feeling unwell and will seek medical check-up.



Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

01
25/5/21