COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

DATE:

27.05.2021

3P INSURANCE: AIG ASIA

MODEL: HYUNDAI IONIQ

NA SURVEYOR:

VEH NO .: SHC3361C

LIM T S MVA:

	PESCRIPTION	QTY	LIST PRICE	REMARKS	
	Rear Bumper	1		\$459.40	/CRK
	Rear Bumper Reinforcement	1		\$394.80	?
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20	?
	Rear Bumper Centre Moulding Assy	1		\$451.25	- DEF
1	Rear Bumper Lower Centre Moulding Assy	1		\$155.00	?
	Rear Bumper Cover Clips	10	\$2.20	\$22.00	NEC
	Rear Bumper Tow Cover	1		\$98.80	XSVL
	Rear Bumper Fog Lamp	1		\$201.50	x svc
	Boot Lid	1		\$2,480.40	XR
	Emblem-Hybrid	1		\$24.30	NEL
	Emblem-loniq	1		\$31.30	MEL
	SPARE PARTS SUB TOTAL			\$4,594.95	
	LESS 20%			\$918.99	
	DISCOUNTED SPARE PARTS TOTAL			\$3,675.96	
					NEC
	Boot Lid ComfortDelGro & 65521111 Stickers	1		\$70.00	/
	Boot Lid Comfort Apps Sticker	1		\$40.00	- NEC
	Rear Bumper Reverse Sensor	1		\$180.00	XSVC
	Rear Windscreen Glasses Sealant	2	\$46.00	\$92.00	X NN /NEC
	Rear No.Plate W/Trim Cover	1	Ď	\$ 55.0 0	NOL
				* 407.00	
	NETT TOTAL			\$437.00	
	SPARE PARTS & NETT TOTAL			\$4,112.96	
				\$800.00	700
	Panel Beating			\$600.00	500
	Spray Painting	1		\$1 20.00	30
	R/I Reverse Sensor			,	XNN
	R/I Both Rear Windscreen Glasses			V	XNN
	Check All Lightings/Wirings			\$40.00	NN
	LABOUR TOTAL			\$1,760.00	
	LABOUR TOTAL			¥ 1,7 30.03	
	ESTIMATE TOTAL			\$5,872.96	
	ESTIMATE TOTAL			, ,,	
			1 1	will be prepared	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance Consultants hence notify

NAZ LKK 27/5/2021 1545 PIP 3 DAY) CHECK HEM PHOTOS

B4 PAINT PHOTOS

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: