

(08/11/13) wef  
ASS. REC. BY: Ram

REF:

CS/CT121006158/Ritz

149F

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMX632K

at Workshop m/s PERFORMANCE

of 303, ALFA ROMEO RD

Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 108K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMX632K Yr Regn: 2018 NSW

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 216 I Gran Tourer c.c 1499

Colour: RED

A/C: Insured / Std / NI / NA

Sp.Reading: 56286

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA6V120306 DOS459

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

205/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/05/21

D.O.I. 07/06/21

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction

Repair limit - 62K

Finalised amount of \$ 8251.65 / 5 days of repair is confirmed

RED: 1832.25; 18%

10083.9

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

) \$ + RS. \$ \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_)

) Photos

☐ : Tech. Invs (\$ \_\_\_\_\_)

) Others

☐ : Weekend (\$ \_\_\_\_\_)

)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 58511  
Date Estimated : 25/05/2021  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

### - ESTIMATE REPAIR FOR -

Woo Foong Yee (Hu FengYi)  
18 Leicester Road  
#18-02

Singapore 358847

### - ACCOUNT - 163385

Ltd. China Taiping

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG632K	WBA6V12030ED05459	30/11/2018	216i Gran Tourer	53222

#### DESCRIPTION

To replace replace rear bumper, tailgate and attachments.

1700 2,550.00

To painting rear bumper and tailgate.

1972 2,076.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To remove and install rear windscreen glass to facilitate repair.

574.00

To conduct water leak tests.

75.00

To carry out body cavity preservation.  
(Per panel).

112 118.00

Sundries.

? 150.00

Total Labour 1: 5,897.00

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,216.40	1,216.40
REAR BUMPER CARRIER	1	460.40	460.40
REAR BUMPER TRIM STRIP (BLACK)	1	72.20	72.20
REAR BUMPER PANEL PRIMED (LINES PDC)	1	1,050.65	1,050.65
LETTERING 216	1	64.75	64.75
GROMMET	2	0.80	1.60
BUMP STOP	1	3.20	3.20
PLAQUE 82MM	1	71.95	71.95
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) WINDSCREEN SEALANT (2 X KLE)	2	175.35	350.70
(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	1	27.85	27.85



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 58511  
Date Estimated : 25/05/2021  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG632K	WBA6V12030ED05459	30/11/2018	216i Gran Tourer	53222

Total Parts : 3,345.85

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 07/06/21 @ 1020 Excess S\$ \_\_\_\_\_

Surveyor's Name Rahul Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	5,897.00
Parts	:	3,345.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	647.00
Grand Total	:	9,889.85

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	19/05/2021 15:31 (SGT)
Date of Accident	18/05/2021 15:00 (SGT)
Exact Location of Accident	3 Penjuru Ln, Singapore 609184
Additional Location Information	Workshop
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG632K
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Woo Foong Yee
NRIC No	SXXXX149F
Email Address	wyee@hotmail.com
Mobile Phone No	(Phone) +65-90011249
Alternative Phone No	+65-90011249

## VEHICLE PARTICULARS

Manufacturer	BMW
Model	216i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1499

## INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MP315370
Cover Note Number	-

## DRIVER

Name of Driver	Ong Kok Peng
NRIC No	SXXXX656B



Date Of Birth	06/03/1980
Occupation	Indoor
Date Of Driving Pass	14/06/2004
Driving experience	16 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91097450
Alt. Phone Number	-
Email Address	ongkokpeng80@gmail.com
Address	18 Leicester Road #18-02
Address complement	-
Postcode	358847
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

Refer to Sketch plan

#### ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2869L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	Goh Jin Kai
Contact Number	(Phone) +65-98292289
Address	-
Address complement	-

Postcode -  
Insurance Company Name -  
Nature Of Damage -  
Details of property damaged in accident -  
No. Of Passenger (Including Driver) -

## SKETCH PLAN

### IMPORTANT NOTICE

VEHICLE NO: 8M G 432 K  
ACCIDENT DATE: 18/5/2021

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**NOTE: DO NOT THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION**

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


18/5/2021

CHARN'S CUSTOMCRAFT

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18 May 2021 3pm ~~Smg 632K~~ Smg 632K Park at Jatai 3 Panjara lane workshop, GBG 2869L lorry reverse bang ~~to~~ Smg 632K backside due to the lorry ~~is~~ was loaded with goods and ~~vision is~~ visibility is low and Rainy day.

OWN DAMAGE ( )    3RD PARTY CLAIM (✓)    REPORTING ONLY ( )    OWN WORKSHOP (✓)

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
If driver is not the policyholder  
Date & Time 19/5/2021

CHARN'S CUSTOMCRAFT  
Reporting Centre Personnel's Signature  
Name  
NRIC ID NO



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	149F
Vehicle No.:	SMG632K
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2021
Vehicle Make:	B.M.W.
Vehicle Model:	216I GRAN TOURER
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	30515373B38A15A
Chassis No.:	WBA6V12030ED05459
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$31,412.00
Original Registration Date:	30 Nov 2018
First Registration Date:	30 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$35,977.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2028
PARF Rebate Amount:	\$26,982.00
COE Expiry Date:	29 Nov 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$30,959.00
COE Rebate Amount:	\$18,694.00
Total Rebate Amount:	\$45,676.00

The Information contained herein is correct as at 07 Jun 2021

OK



# BMW 2 Series 216i Gran Tourer

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

## Republic Auto



A member of the Jardine Cycle & Carriage Group

**Price** **\$109,800**

**Depreciation** ?

\$12,140 /yr

[View models with similar depre](#)

**Reg Date**

28-Dec-2018

(7yrs 6mths 20days COE left)

**Mileage**

34,176 km (14k /yr)

**Manufactured** ?

2018

**Road Tax** ?

\$684 /yr

**Transmission**

Auto

**Dereg Value** ?

\$46,266 as of today (change)

**OMV** ?

\$31,412

**COE** ?

\$25,501

**ARF** ?

\$35,977

**Engine Cap**

1,499 cc

**Power**

80.0 kW (107 bhp)

**Curb Weight** ?

1,490 kg

**No. of Owners** ?

1