

Certification for Bus Repairs



CBR REF NO. : HG20212703

Depot : HG Report No.: W19182021 BUS VEHICLE NO. : SG5853K
 Driver's Co no. & Name : 60828 Wang Chaowei
 Accident Date : 29/04/2021

Date in : 29/04/2021

Date Out : 04/06/2021

Yr Of Reg	Make / Model	Chassis No.
2017	MAN A95 EU5, DD, AC, 3 Axle	WMAA95ZZ9G7003525

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30400212	REFLECTOR	1	<i>cra</i> ✓ \$12.00
30400176	ENGINE DOOR.RR.FRP	1	<i>XR</i> \$747.00
30400172	COVER.FRP HEADLAMP.REAR N/S	1	<i>cra</i> ✓ \$390.00
30400211	STICKER REFLECTOR.RIGHT.LTA 122 BATCH 1	1	<i>rec</i> ✓ \$55.00
30400258	LAMP.LED.CENTRE BRAKE.2BA 959 071-777	1	<i>cra</i> ✓ \$110.00
30400210	STICKER REFLECTOR.LEFT.LTA 122 BATCH 1	1	<i>rec</i> ✓ \$55.00
30400176	ENGINE DOOR.RR.FRP	-1	<i>XRepeated</i> (\$747.00)
30400459	ENGINE DOOR.RR.COMPLETE.A95.E5	1	<i>bt</i> ✓ \$1,500.00
30400257	LAMP.REVERSE.(BULB)	1	<i>cra</i> ✓ \$98.00
30541770	LED.TAIL/STOP LAMP.RR.LH/RH	1	<i>cra</i> ✓ \$104.00
30400213	LAMP HSG W/OUT BULB.FOG.RR	1	<i>cra</i> ✓ \$98.00
30541771	LED.SIGNAL LAMP.RR.LH/RH	1	<i>cra</i> ✓ \$150.00
TOTAL FOR PARTS			S\$ 2572.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$ <i>X n n</i> 192.00	
2	Contractor's repair charges	S\$ 2200.00	
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 2392.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 4964.00

Certification for Bus Repairs



CBR REF NO. : HG20212703

Depot : HG Report No.: W19182021 BUS VEHICLE NO. : SG5853K
 Driver's Co no. & Name : 60828 Wang Chaowei
 Accident Date : 29/04/2021

Date in : 29/04/2021

Date Out : 04/06/2021

Yr Of Reg	Make / Model	Chassis No.
2017	MAN A95 EU5, DD, AC, 3 Axle	WMAA95ZZ9G7003525
TOTAL DAMAGE		S\$ 4964.00
Overheads		X^n S\$ 1489.20
Towing Charges		S\$ -
Repair Period : 6 day(s)	Loss of Use	X^n S\$ 2565.84
TOTAL LOSS		S\$ 9019.04

Prepared By : Zakaria Bin Ahmad

Date : 26/06/2021

Approved By
Workshop Mgr : Aw Boon Huan

Date : 29/06/2021

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 9019.04

Acknowledged By
Depot Safety : Ang Kiat Siang

Date : 29/06/2021

* This is computer generated document and does not require signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6 days

TAUFIKH
"WP" 31/5/21 @350PM
RESURVEY NEW PARTS
6 DAYS