

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 205470613  
Date : 27.05.21  
Time of Fax : \_\_\_\_\_

Via Fax : EMRLL  
Your Insured : SMV 7759D  
Date of Acc : 24.05.21

Attn: Motor Claims Department

ALG

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

8611S

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ <b>Chiang Liat Choon</b>	<b>Tel: 6214 8314 or HP: 9296 6006</b>

} **chiangle@cdge.com.sg**  
**Fax no. 6546 8156**

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

  
For Vice President  
Taxi Accident Repair

**REPAIR ESTIMATE\***

VEHICLE NO SH8611S

DATE 25/05/2021

MAKE :

MODEL : HYUNDAI IONIQ G2

CHIANG /AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$430.90
1	FROBT BUMPER BRACKET RH			\$35.00
1	FRONT HEADLAMP ASSY RH			\$1,993.65
1	FRONT FENDER RH			\$588.80
1	FRONT FENDER SHIELD RH			\$164.70
1	FRONT FENDER EMBLEM			\$26.60
1	FRONT BUMPER GRILLE RH			\$186.90
1	FRONT DOOR PROTECTOR RH			\$186.20
1	FRONT DAY LIGHT RH			\$642.50
1	FRONT WHEEL COVER RH			\$368.50
	<b>SUB TOTAL</b>			<b>\$4,623.75</b>
	<b>20.00%</b>			<b>\$924.75</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$3,699.00</b>
				<b>\$-</b>
	<b>Labour Charge</b>			
	Panel Beating			\$750.00
	Spray Paint			\$600.00
	Reset front wheel alignment			\$90.00
	Check lighting			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,500.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$5,199.00</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	25/05/2021 19:57 (SGT)
Date of Accident	24/05/2021 16:30 (SGT)
Exact Location of Accident	Toa Payoh Rise, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH8611S
-----------------------------	---------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-96611843
Alternative Phone No	(Office) +65-65508768

#### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

#### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

#### DRIVER

Name of Driver	TAN YEOW CHIM
NRIC No	SXXXX641G

Date Of Birth	04/12/1970
Occupation	Outdoor
Date Of Driving Pass	19/10/1993
Driving experience	27 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96611843
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 702 PASIR RIS DRIVE 10 #05-121
Address complement	-
Postcode	510702
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	UNKNOWN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON 240521 AT AROUND 1630HRS, I WAS DRIVING MY VEHICLE A SH8611S ALONG TOA PAYOH RISE ON THE LEFT LANE. THE ROAD WAS UNDER CONSTRUCTION AND I WAS NEGOTIATING A LEFT BEND. SUDDENLY VEHICLE B SMV7759D CAME INTO MY LANE AND SIDE SWIPE MY FRONT RIGHT WHEEL ARCH AREA. THERE WAS SOME DAMAGE ON THAT AREA. THERE WAS NO INJURIES.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE NOT SUITABLE.
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMV7759D
Vehicle Manufacturer	-

Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

Private car

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time 25/5/21 1120

Witnessed by Reporting Centre Personnel KHAIRUL

**Sketch Plan**

## Describe Circumstances of the Accident

ON 240521 AT AROUND 1630HRS, I WAS DRIVING MY VEHICLE A SH8611S ALONG TOA PAYOH RISE ON THE LEFT LANE. THE ROAD WAS UNDER CONSTRUCTION AND I WAS NEGOTIATING A LEFT BEND. SUDDENLY VEHICLE B SMV7759D CAME INTO MY LANE AND SIDE SWIPE MY FRONT RIGHT WHEEL ARCH AREA. THERE WAS SOME DAMAGE ON THAT AREA. THERE WAS NO INJURIES.

## Declaration

I/We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature / Date &  
Time

\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date  
& Time 25/5/21 1120

\_\_\_\_\_  
Witnessed by Reporting Centre  
Personnel KHAIRUL

