

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508999
Fax: 6546 8156

Our Job Ref No : 305470613
Date : 06/01/21

FINALIZATION FORM

To : LKK
Attn : NAZ
Vehicle Reg No. : SH 8611S

Fax :

24/05/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: AIG SMV7759D
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$787.12</u> |
| (b) Labour Charges | <u>\$1,200.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,987.12</u> |
| (c) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : Nil
Name : NAZ LKK
Date : 2/6/2021

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|---------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | - | N | | |
| 3. Survey Fees | - | - | | |
| 4. LTA Search Fee | \$7.49/\$2.00 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

MAZ RICH

COMFORTDELGRO ENGINEERING PTE LTD

Date: 31.05.2021

REPAIR ESTIMATE

Time: 11:09:34

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305470613
REGN NO : SH 8611S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 29.04.2021
DATE/TIME IN : 24.05.2021 17:25
ACCIDENT DATE : 24.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

| | | | | | | |
|------------------------|----------------------|---|--------|-------|--------|-------|
| 0001 04-01-0104-0573-G | PANEL-FENDER RH# | 1 | 588.80 | 20.00 | 471.04 | ✓ DD |
| 0002 04-01-0104-3913-G | EMBLEM-BLUE DRIVE RH | 1 | 26.60 | 20.00 | 21.28 | ✓ NEL |
| 0003 03-01-0104-2137-G | CAP ASSY-WHEEL HUB | 1 | 368.50 | 20.00 | 294.80 | ✓ SCR |

SUB-TOTAL : 787.12

JOB NATURE

| | | | |
|---------|-------------------|--------|---|
| 0000 PB | PANEL BEATING | 700.00 | ✓ |
| 0001 SP | SPRAYPAINT CHARGE | 500.00 | ✓ |

SUB-TOTAL : 1,200.00 ✓

TOTAL : 1,987.12

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

CHIANG /AIG

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.