

Your Ref: CMTD1802664/THE

Date: 11th June 2021

Our Ref: CS1/LAW21006181/Gtf3e2

M/s Sompo Insurance Singapore PL

C/o : Chey LLC

20 Havelock Road

#02-47 Central Square

Singapore 059765

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLF 2344X
INSURED VEHICLE: SLB 1740M
ACCIDENT DATE: 22/06/2018**

We thank you for your instruction on 27/05/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLF 2344X from M/s C L Appraiser Pte Ltd.
- b) Survey report by Priority Services with colour photographs.
- c) Singapore Accident Statement of Vehicles SLF 2344X and SLB 1740M.
- d) Colour damaged vehicle photographs of SLF 2344X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLF 2344X
Make & Model	: Honda Mobilio SV 1.5 CVT
Chassis Number	: MRHDD4870GP000231
Year of Registration	: 2016
Engine Capacity	: 1497 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.