

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196K GS1 Reg. No. 19-900/196-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21006182/Kvf3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	05/07/2021	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLA 335L	Veh. Inspected		SLL 1240L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010354/ST	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		27/05/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI LANCER (A)	c.c		1590	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JMYSRCY1AGU006293	Colour		METALLIC GREY	
	Odometer	180726 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	DAVANTI		8 mm	
	L/H Front Tyre	205/60 R16	DAVANTI		8 mm	
	R/H Rear Tyre	205/60 R16	DAVANTI		8 mm	
	L/H Rear Tyre	205/60 R16	DAVANTI		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/05/2021	Inspection Date		28/05/2021	
	Survey held at	KUM CHEW MOTOR WORKSH	OP			
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: