

## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated : 25/05/2021
User ID : JeongCH

4.6.7.1.2.1.2.1.2.1.2.1.2.1.2.1.2.1.2.1.2.1		Section A - Accident Details		
Registration Number		SMB350A	500	_
Case Reference Num	ber	BUS/05/21/5038		_
Registration Date		11/20/2012		_
Company Type		SMRT Buses Ltd		_
/lake	44 C 100 C 1	MAN		_
Model		A22		_
lame of Driver	1	Tan Siew Choo		_
ype of Accident	70 5	Head To Side		_
Accident Date and Tir	y King and a state of the state	5/19/2021 11:32 PM		_
ccident Reported Da		5/22/2021 9:56 AM		_
Surveyor Required	?	No		_
survey by				_
ehicle is Towed Bac		No	Fi.	
owed Back Date and	1 (275) (37)			_
Replacement Vehicle	issued?	No		
ob Card Number				
pecial Instruction to	ARC,if any	SMB350A-LEFT REAR TYRE SCRATCH	ES	
Prepared Date and Ti	ime	SGG7988J (TP) INSURED WITH AIG 5/24/2021 6:46 PM		-
Chassis Number		WMAA22ZZ2C7001516		$\dashv$
Aileage		**************************************		-
Vork Shop		+		$\dashv$
CONTRACTOR OF THE PARTY OF THE	ate and Time	-		$\dashv$
epair Completion Da		1	- Constitution of Constitution	_
MAN TON	NAMES OF TAXABLE PARTY OF TAXABLE PARTY.	Section B - Summary of Repair Est	imates	
ummary of Repai	r Estimates		and the second second	
	2	Quotation from ARC	Adjusted by Surveyor, if applicable	
otal Labour Cost	- <del> </del>	\$530.00	\$0.00	⊣
otal Spray Cost		\$694.00	\$0.00	┥
otal Spare Part Cost		\$0.00	\$0.00	$\dashv$
otal Other Cost		\$0.00	\$0.00	$\dashv$
OTAL COST		\$1,224.00	\$0.00	$\dashv$
ump Sum Total		\$0.00	\$0.00	$\dashv$
A CATALOG DE SENSE SE SE LA CATALOG DE SE	2.5 (a. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	2.0	1	$\dashv$
umber of Repair Day repared / Adjusted B	CONTRACTOR OF THE PROPERTY OF	Jeong Choon Hwee		$\dashv$
TOTAL COLUMN		24/05/2021 6:49 PM		$\dashv$
RC / Surveyor Sign (	Un Date	24/U3/2U21 0:49 PM	[X]	$\dashv$
ignature			ſ	
emarks				1
Г	14) (* * ra	count cincil and Column NA to	7	
	17.701	trend to the property of the production	Specific Control of the Control of t	2.04
	Sect	ion G Quotation and Accident lave		
otation Number	T	Invoice Number	A CONTRACTOR OF THE CONTRACTOR	edition
otation Date	1.2	E The Deporte Involce Date *		7
roice Amount		of toelcars are this paradobine		-
J.Se Amount	sized felt to st	Third party survey is on a "X" >	1	<b>-</b>
		No illegal modification(S) is a least	1	
age 1 of 2	tops bayerous	Supplementary trends to the property of t		
Andre Spirite Control of the Control		Acknowledged by Repare: Signature:		
l-me.	- The said Margaret away by processing	Date:	1	



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number : 68662672

Date Generated : 25/05/2021

User ID

: JeongCH

444				Section D - Deta	alls of Repair I	stimates					
art 1 - Labor	ur Works										
ob Scope				Quotation f	Quotation from AR			Adjusted by Surveyor, if applicable			
O REPAIR LEFT REAR PORTION				\$530.00	\$530.00				265		
otal Labour				\$530.00	\$530.00				- 607		
art 2 - Spray	Painting & P	anel Beating Rela	sted Works					77	S S S S S S S S S S S S S S S S S S S		
ob Scope			Quotation f	Quotation from ARC			Adjusted by Surveyor, if applicable				
O PUTTY & RESPRAY				\$694.00	\$694.00				524		
otal Spray Painting & Panel Beating				\$694.00	\$694.00						
art 3 - Other	Costs - Accid	dent and Acciden	t Repair Related I	Expense				E. Albania			
ob Scope				Quotation f	Quotation from ARC				Adjusted by Surveyor, if applicable		
otal Other Costs									180 - 170 -		
art 4 - Spare	Parts / Mater	rial Usage			6						
art Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved		
otal			portions for the stage (12)	1961.12.194					0.00001		
dded Spare	Parts / Materi	ial Usage After Su	rveyor Signed of	ſ	·	•	•	7			
art Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check		
otal	A STATE OF THE STA	LANGE CONTRACTOR OF THE PARTY O		2227		(1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -					
						1	1	1	1		

10 ay.
Como Qiang - 82880282
(UKK)
25/5/21
After pant phas.

## LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting • To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: