



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD YAMAHA AEROX 155A (FBR4370L)
Date of Loss	21 May 2021
Time of Loss	16:15
Loss Description	FBR1985H (INSD) C/W FBR4370L (TP) which parked at parking lot
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	-\$3,445.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# FBR4370L

Registration State

SINGAPORE

Mileage

36915

Purchase Date

DD/MM/YYYY



Registration Date *

30/06/2020



Age of Vehicle

0

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2020

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

CHAN WAI MENG
MELVIN

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD YAMAHA	<input type="text" value="YAMAHA"/>
Model	AEROX 155A	<input type="text" value="AEROX 155A"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MLESG584111050360"/>
Engine No		<input type="text" value="G3M1E050333"/>
Engine Capacity		<input type="text" value="155"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

31/05/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

100-80-14

Front left side

MAXXIS6mm

Front right side

Spare wheel

Rear Tyre Size

120-80-14

Rear left side

PIRELLI6mm

Rear right side



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition








Taxes & Ratio











Parts & Labour

Miscellaneous

Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	APPROVAL (F)
	0	1		FRONT FORK ASSY	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		FORK UNDER BRACKET	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		FRONT SPORT RIM	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		FRONT BRAKE DISC	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		FRONT RIM SHAFT	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		SET SIDE MIRROR	Cut	0	120	No	0	10	0	0	108	R
	0	1		HANDLE-BAR	Serviceable	0	0	No	0	0	0	0	0	D

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	Av (F
	0	1		SET HANDLE-BAR BALANCER	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		SET HAND GRIP	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		BRAKE LEVER N/S	Damaged	0	52	No	0	10	0	0	46.8	R
	0	1		BRAKE LEVER O/S	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		RADIATOR COVER	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		FOOTSTEP PANEL N/S	Cut	0	205	No	0	10	0	0	184.5	R
	0	1		FOOTSTEP PANEL LOWER COVER N/S	Cut	0	160	No	0	10	0	0	144	R
	0	1		EXHAUST ASSY	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		EXHAUST PROTECTOR	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		SET FAIRING COVER	Cut	0	900	No	0	10	0	0	810	R







Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING	0	0	0	0	Deny		
	0		TO REPAIR BODY FRAME	0	0	0	0	Deny		
	0		TO PROVIDE LABOUR	0	250	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition















Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 3 DAYS	Reviewing	0	0		
	0	1 SET NUMBER PLATE	Reviewing	0	10	FRONT NECESSARY	
	0	FORK OILS (2PCS)	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FORK OIL SEALS (2PCS)	Deny	0	0	NOT NECESSARY	
	0	1 SET STEERING CONE	Deny	0	0	NOT NECESSARY	
	0	FRONT SLIDER	Deny	0	0	NOT NECESSARY	
	0	REAR SLIDER	Deny	0	0	NOT NECESSARY	
	0	REAR BOX	Deny	0	0	NOT NECESSARY	
	0	REAR BOX BRACKET	Deny	0	0	NOT NECESSARY	
	0	1 SET STICKER	Reviewing	0	80	NECESSARY	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$1,633.30
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$1,293.30
Labour	\$0.00	\$250.00
Miscellaneous	\$0.00	\$90.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	1300		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$1,300.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$1,300.00

Submit for Review