ASS. REC. BY: Steve | REF: CS3/ASM2190 6216/EVC

ASSIGNMENT

PRS

From: Date:

Estimated Cost:

OD / (TP) / WS / TP RES / OD-RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SHA 3745P

Policy No.

Claims No. S1M03AMJ

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBR 589A Yr Regn: 20/2/20

Type: M.Car / (M.Cycle) / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Yamaha CZD300A c.c 292

Colour: Silv.

A/C: Insured / Std / Nil / N

T/Radio: Insured / Std / Nil / N

Sp.Reading: 14756

Eng/No:

C/No: MH3SH0848 KK 00 7284

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 120/70-15

R: 140/70-14

BS / (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: R/Bal. 4 mm; L/Bal. mm

Rear: R/Bal. 4 mm; L/Bal. mm

D.O.A. 12/5/21 D.O.I. 4/6/21

Survey held at M1 Motoring

Des. of Damages: Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV- 16K Repair range 3K - 4K
	4 repair days
4/6/21	Submit PRS -Repair range $3000-$4000

Date/Time, File Pass to?: [ ] : Prell. Report

[ ] : Final Report

Date/Time, File Return to?

4/6/21-Typist

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($)

[ ] : Interview ($)

[ ] : Tech. Inve ($)

[ ] : Weekend ($)

Survey Fee:

Transportation: S + RS ___ SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.P.I./C: