



Service Requests

Messages

Claims



Service Request Details

Claim	S1M03AIY
Reference	CS3/ASM21006230/T1qce2 
Loss Date	16 May 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	24 May 2021 8:50:11 AM
Request Date	31 May 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident FBP9527E
Vehicle
Registration #

Make TPVD

Model YAMAHA

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

YU Dominic Yishan

dominic.yuys@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2104024.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	9 June 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	9 June 2021
 FBP9527E Inspection Photos_compressed.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	2 June 2021
 AXA Immediate Advice - FBP9527E (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 June 2021
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	31 May 2021
 SHA7185D INS.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	24 May 2021
 FBP9527E TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	24 May 2021
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	24 May 2021