

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305470935
Date : 29/05/21

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SH 9715U

Date of Accident : 27/05/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- YP 712Z
###
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$1,113.36</u> |
| (b) Labour Charges | <u>\$211.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,324.36</u> |
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,050.00
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 1 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : [Signature]

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : [Signature]

Name : NAZ LKK

Date : 26/6/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	--	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 29.05.2021

Time: 10:45:18

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305470935
REGN NO : SH 9715U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 05.07.2018
DATE/TIME IN : 28.05.2021 10:25
ACCIDENT DATE : 27.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2537-G MIRROR ASSY-O/S RR VIEW L 1 1,391.70 20.00 1,113.36 / MIS

SUB-TOTAL : 1,113.36

JOB NATURE

0000 PB	PANEL BEATING	100.00	/
0001 SP	SPRAYPAINT CHARGE	100.00	/
0002 L	MERIMEN FEE	11.00	/

SUB-TOTAL : 211.00

TOTAL : 1,324.36 /

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/05/2021
Vehicle Reg. No.:	SH9715U	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	05/07/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU046149	Chassis No:	KMHC851CVJU103438
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,113.36
Miscellaneous Items	11.00
Labour	240.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,364.36
+ GST 7.00% (S\$)	95.51
Nett Amount (S\$)	1,459.87

This claim is handled by: JUMANI BIN MASUDIN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH9715U/28/05/2021 13:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT LH SIDE MIRROR ASSY	20.00	0.00	*1,391.70 FL <i>MIS</i>
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)						1,391.70
- List Item Discount on L Items (\$\$)						278.34
Total Parts (\$\$)						1,113.36

ComfortDelGro Engineering Pte Ltd/SH9715U/28/05/2021 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2021

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	RENEW FRT SIDE MIRROR LH	New	100 120.00
2	SPRAYPAINT	New	100 120.00
Gross Labour Cost (S\$)			240.00

ComfortDelGro Engineering Pte Ltd/SH9715U/28/05/2021 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKK
28/5/2021 1630
PIP
1 Day
BY PAINT PHOTOS

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: