

REF: CS3/ASM21002912/T1qf3-1

Special Instruction:

ASSIGNMENT (Office)

LS \$37900

From (Person): Tan Jun Hong of AXA Date/Time: 31/05/2021

Third Parties:

Estimated Cost: _____ Bill to: _____

Claimant:

OD TP Re-inspection / Evaluation

Surveyor: CL Appraiser PL

To inspect Vehicle No: SMT 9516K Insured: SHC 1392B

Workshop: Alpha Car Services PL

at Workshop m/s Alpha Car Services PL Tel:

of BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883

Policy No: _____ Claim No: **S1M034B3**

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/03/2021
(Client's Record)

(Client's Record) _____ D.O.A. 01/03/2021
Appt 02/06/21@11am at Fong Motor 1 KAKI BUKIT AVE 6 #01-27/01-45 S(417883)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original 38 days)

Date/Time: 24/06/21 Submit ~~Final Fig~~ LS \$24100, 20 days (Red \$ 13800/36 %; Original 38 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
---	--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 24/06/21 File Pass to Typist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____