

ASS. REG. BY:

Steve

REPT

AIG

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Cum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMM 6283 M

Yr Regn:

8/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c

1591

Colour:

Grey

A/C:

Insured / Std / NI / N

Sp. Reading

12607

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNAF3416 MK5046337

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

18/5/21

D.O.A.

31/5/21

Survey held at

Cycr &amp; carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

F1 RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-73K

Date/Time, File, Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Inve

(\$

☐

: Weiband

(\$

\$ + RS \$

Phone

Others

TOTAL

Approved:

Date/Time/Signature

## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /YEO LENG QUEE (YANG LONGGUI) Reg No/Reg Date SMM6283M*KC17/ 08/07/201 Date In/Mileage 31/05/2021/ 0 Chassis No KNAF3416MK5046337 Engine No G4FGKH740819 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	31/05/2021/ 16:14	QUC	442 / CocoLu	34027		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT SUPPORT PANEL REPAIR ON FRT FENDER (LH) & RH & BONNET				1 X 400			400 1200.00
E PNT98000 SPRAY PAINT WORK ON FRT BUMPER, FRT LH FENDER, BONNET & AFFECTED AREAS				3 X 350			1050 1400.00
E PNT88000 TO REMOVE AND INSTALL FRT PARKING ASSIST SENSOR							80.00
M SUNDRY TO PERFORM RUST PREVENTION							80.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME							50.00
M SUNDRY SUNDRIES							70 50.00
M	COVER-FR BUMPER	BR		1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER	CUT (black)		1.00	485.00	20.00	388.00
M	GRILLE ASSY-RADIATOR			1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE	BR		1.00	38.00	20.00	30.40
M	COVER-FR BUMPER FOG LAMP, RH	BR CUT		1.00	15.00	20.00	12.00
M	MOULDING-FRONT BUMPER, RH	BR		1.00	216.00	20.00	172.80
M	ABSORBER-FRONT BUMPER ENERGY			1.00	84.00	20.00	67.20
M	BEAM COMPLETE-FR BUMPER			1.00	497.00	20.00	397.60
M	CARRIER ASSY-FRONT END MODULE			1.00	675.00	20.00	540.00
M	ORNAMENT-KIA NO.115	nec		1.00	32.00	20.00	25.60
M	LAMP ASSY-HEAD, RH	CUT		1.00	2210.00	20.00	1768.00
M	LAMP ASSY-SIDE REPEATER, RH	CUT		1.00	143.00	20.00	114.40
M	STIFFNER-FR BPR LWR			1.00	114.00	20.00	91.20

Estimate

Stere (CLKK)

31/5/21, 4:30pm

OD- M1 AL

Excess - ?

Confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

P/P, M Bel SM

4 dys

7% GST on

Nett

7386.00

7,386.00

517.02

Total Payable

7,903.02

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	31/05/2021 14:16 (SGT)
Date of Accident	18/05/2021 15:30 (SGT)
Exact Location of Accident	Near Unnamed Road, Singapore
Additional Location Information	BLK 102A RIVERVALE WALK
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM6283M
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	YEO LENG QUEE
NRIC No	SXXXX464C
Email Address	yeo.leng.quee@gmail.com
Mobile Phone No	(Phone) +65-98511866
Alternative Phone No	+65-98511866

### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900109989
Cover Note Number	-

### DRIVER

Name of Driver	YEO LENG QUEE
NRIC No	SXXXX464C



Date Of Birth  
Occupation  
Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

28/06/1971  
Indoor  
22/09/1992  
28 YEARS AND 8 MONTHS  
Male  
(Phone) +65-98511866  
+65-98511866  
yeo.leng.quee@gmail.com  
BLK 109 RIVERVALE WALK #07-24  
-  
540109  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Hit and run / Vandalism / Damaged whilst parked  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No  
2  
No  
-  
Yes  
0  
No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Police Station Name  
Police Station Phone No  
Alt. Police Station Phone No  
Police Station Address  
Was notice of intended Prosecution given?  
If yes, against whom?

Yes  
Ang Mo Kio Division Headquarters  
(Phone) +65-18002180000  
(Fax) +65-64814246  
51 Ang Mo Kio Avenue 9 Singapore 569784  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?

Yes  
No  
No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category

UNKNOWN  
-  
-  
-  
-  
Private car

Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


### 8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "**Purposes**")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan





**Describe Circumstances of the Accident**

Refer To Police Report

**Declaration**

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel



# SINGAPORE POLICE FORCE



F/20210528/7010

1 of 2

## POLICE REPORT (NP299)

Report No. F/20210528/7010

Police Station Of Origin  
Ang Mo Kio Division HQ  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No:1800-2180000

Date/Time Report Made 28/05/2021 10:17	Vide Report No.		Station Diary No.	
Name Of Informant TEO SWEE CHOO PAULINE	Address 109 RIVERVALE WALK #07-24 SINGAPORE 540109			
ID Type / ID No. NRIC NO / S 8543E	Contact No. Home/Office:		Mobile: 97451436	
Nationality SINGAPORE CITIZEN	Email Address Ice Scorpiogal@yahoo.com.sg			
Occupation Housewife	Sex Female	Age 46	Date of Birth 16/11/1974	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 18/05/2021 15:00 - 27/05/2021 19:00	Location Of Incident 102A RIVERVALE WALK #1B MULTI STOREY CAR PARK SINGAPORE 541102			

### Brief details.

Our car was parked at Sengkang BLK 102A carpark SK4 in a season lot at level 1B. Vehicle number SMM6283M. The last time we drove the car was on Tue, 18 May 2021. After parking there at 3 plus in the afternoon, we never used it until yesterday evening, 27 May. My husband went to start the engine at 6 plus in the evening. As he approached the car, he noticed it was shifted slightly, then he saw the front right of the bonnet was badly damaged. The light and sensor are not working anymore. He drove the car to another more secluded lot before taking pics of the damage.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 28/05/2021 10:17
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	





# SINGAPORE POLICE FORCE



F/20210528/7010

2 of 2

POLICE REPORT (NP299)

## CONTINUATION OF REPORT

Report No. F/20210528/7010

No notes were found. He even went around to see if any car had damages that might have caused our car's damage, but couldn't see any. I called HDB branch to check if there are any camera footages that could help us identify the culprit but was asked to make a police report.

I have pics but not able to upload them at all. It just hangs there when I tried to upload. I tried several times already.

Subjects Involved			
Victim			
Person Name	TEO SWEE CHOO PAULINE		
ID Type	NRIC NO	ID No	S <del>77</del> 543E
Gender	Female	Age	46
Race	Chinese	Language	English
Occupation	Housewife	Address	109 RIVERVALE WALK #07-24 SINGAPORE 540109
Mobile No	97451436	Is Informant A Victim?	Yes
Person Name			
TEO SWEE CHOO PAULINE (Informant)			

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 28/05/2021 10:17
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

# CERTIFICATE OF INSURANCE

## AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : YEO LENG QUEE (YANG LONGGUI)  
Period of Insurance : 08 Jul 2019 To 07 Jul 2021  
Engine No. : G4FGKH740819  
Chassis No. : KNAF3416MK5046337

Vehicle No. : SMM6283M  
Policy No. : 1900109989  
Endorsement No. :  
Issued Date : 12 Jul 2019

### ABOUT THE COVER

Make/Model : KIA Cerato  
Engine Capacity/Tonnage : 1,591.00 CC  
Driver Restriction : NA  
Person or Classes of Persons Entitled to Drive\* :  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2019  
Insuring with COE/PARF : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

#### Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YEO LENG QUEE (YANG LONGGUI) - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622210

C&CKICP2 - JAMES  
239 ALEXANDRA ROAD  
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

  
AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

SSC2S: