

08/11/13) wef

ASS. REC. BY: Paul

REF:

CC3/AH21006281/R1f3

7294

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMP 20444at Workshop m/s PREMIUMof 24, House sector

Insured:

AH

Policy No.

1900162090

Claims No.

5733512991SG

Sum Insured:


Excess:

TBA 600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

101K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMP 20444

Yr Regn:

2014 18EP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 SPB 1.0 TFSI S-T c.c 999

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

17846

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WA U2228V5 LA 00 2854

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/05/21

D.O.I.

31/05/21

Survey held at

PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 58Kconfirm repair cost of \$3252.00 @ 5 days
RED: 10335;76%

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

5

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) S + RS SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0460/2021/TF
DATE : 29-May-21
WIP : 29181

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : SMP 2044 Y
ADDRESS : 80 LORONG K TELOK KURAU
#02-03
SINGAPORE 425710
TELEPHONE : HP +65 88281313
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900162090
VEHICLE NO : **SMP 2044 Y**
MODEL CODE : A3 SPORTSBACK 1.0 TFSI
MODEL YEAR : 16/9/2019
ENGINE NO : CHZ C35215
CHASSIS NO : WAUZZZ8V5LA002954
MILEAGE : 17845KM
DATE IN : 28-May-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-May-21
PLACE OF ACCIDENT : AIRPORT RD LEADING TO KPE TUNNEL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 2044 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00 ✓	
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00 X	
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1.5 \$	2,450.00 750	
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR. @ 550x3 + 100	\$	3,000.00 1750	
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 6,552.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 2044 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>repair</i>	1	\$ 2,070.00	
2	REAR BUMPER ADAPTER - LH <i>X</i>	1	\$ 38.00	
3	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 67.00	
4	REAR DOOR - LH <i>repair</i>	1	\$ 2,767.00	
5	REAR DOOR OUTER SEAL - LH <i>X</i>	1	\$ 161.00	
6	BONDING AGENT <i>X</i>	1	\$ 49.00	
7	CLEANING SOLUTION <i>X</i>	1	\$ 68.00	
8	APPLICATOR <i>X</i>	1	\$ 8.00	
9	REAR DOOR CATCH - LH <i>X</i>	1	\$ 94.00	
10	REAR WHEEL HOUSING LINER - LH <i>X</i>	1	\$ 240.00	
11	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i>	1	\$ 57.00	
12	REAR TYRE RIM - LH <i>repair (polish)</i>	1	\$ 1,166.00	
13	SUNDRIES <i>?</i>	1	\$ 250.00	
TOTAL SPARE PARTS		:	\$ 7,035.00	
TOTAL LABOUR CHARGES		:	\$ 6,552.00	
GRAND TOTAL		:	\$ 13,587.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasul - Hp 90010068
: 31/05/21 @ 1130
: 5 days
: excess: TBN
: Revert
: Resurvey after repair

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/05/2021 15:26 (SGT)
Date of Accident	27/05/2021 18:45 (SGT)
Exact Location of Accident	Airport Rd, Singapore
Additional Location Information	AIRPORT ROAD LEADING TO KPE TUNNEL (BEFORE YELLOW BOX OF LANE)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMP2044Y

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	YEOW CHIEN HWEE
NRIC No	SXXXX729H
Email Address	EDDYYEOW@YAHOO.COM
Mobile Phone No	(Phone) +65-88281313
Alternative Phone No	+65-96256982

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	999

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900162090
Cover Note Number	-

DRIVER

Name of Driver EVELYN LEONG SU LING

NRIC No	SXXXX907H
Date Of Birth	01/05/1974
Occupation	Indoor
Date Of Driving Pass	25/03/1994
Driving experience	27 YEARS AND 2 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96250982
Alt. Phone Number	-
Email Address	SOULING010@YAHOO.COM
Address	BLK 128 RIVERVALE STREET
Address complement	#05-832
Postcode	540128
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	YEOW CHIEN HWEE
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AT AROUND 6.45PM, EVELYN DROVE SMP2044Y ALONG AIRPORT ROAD HEADING TO KPE TOWARDS SENGKANG ESTATE. THE TRAFFIC WAS SLOW BUT ORDERLY. SMP2044Y WAS ON THE MERGING LANE AND JUST BEFORE THE YELLOW BOX, SFA9173Z ACCELERATED AND DID NOT MAINTAIN THE SAFETY AND THUS HITTING AND BRUSHING THE BACK, LEFT SIDE OF SMP2044Y.

THE DRIVER OF SFA9173Z DID NOT PROVIDE HIS PARTICULARS AND WE COULD ONLY CAPTURE PHOTOGRAPHS OF THE AFTERMATH.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFA9173Z
Vehicle Manufacturer	Suzuki
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature] 28/5/21

Policyholder's Signature / Date &
Time 9.31 am


Sketch Plan

[Signature] 28 May 2021

Driver's Signature (If driver is not the policyholder) / Date
& Time 9.50 am



Witnessed by Reporting Centre
Personnel Tony Foong



Describe Circumstances of the Accident


At around 6.45pm, Evelyn drove SMP 2044Y along Airport Road heading to KPE towards SungKang estate.


The traffic was slow but orderly. SMP 2044Y was on the merging lane and just before the yellow box, SFA 9173Z accelerated and did not maintain the safety distance and thus hitting and brushing the back, left side of SMP 2044Y.

The driver of SFA 9173Z did not provide his particulars and we could only capture photographs of the aftermath.

Declaration

We declare the foregoing particulars are true in every respect.

 28/5/21
Policyholder's Signature / Date &
Time 9.30am

 28 May 2021
Driver's Signature (if driver is not the policyholder) / Date
& Time 9.30am



Witnessed by Reporting Centre
Personnel Tony Foong

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	729H
Vehicle No.:	SMP2044Y
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jun 2021
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	CHZC35215
Chassis No.:	WAUZZZ8V5LA002954
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$21,552.00
Original Registration Date:	16 Sep 2019
First Registration Date:	16 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$22,173.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2029
PARF Rebate Amount:	\$16,629.00

COE Expiry Date:	15 Sep 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,783.00
COE Rebate Amount:	\$26,344.00
Total Rebate Amount:	\$42,973.00

The information contained herein is correct as at 01 Jun 2021

OK

Audi A3 Sportback 1.0A TFSI S-tronic

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price **\$99,900**

Depreciation  **\$10,900 /yr**
[View models with similar depre](#)

Reg Date **24-Jul-2019**
(8yrs 1mth 22days COE left)

Mileage **25,000 km (13.5k /yr)**

Manufactured  **2019**

Road Tax  **\$392 /yr**

Transmission **Auto**

Dereg Value  **\$38,358 as of today ([change](#))**

OMV  **\$21,552**

COE  **\$26,667**

ARF  **\$22,173**

Engine Cap **999 cc**

Power **85.0 kW (113 bhp)**

Curb Weight  **1,275 kg**

No. of Owners  **1**

Type of Vehicle **Hatchback**