

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                                          |                        |                |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|------------------------|----------------|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                               |                                                                                          |                        |                |
| SMRT AUTOMOTIVE SERVICES PTE LTD                                                                                                       |                                                                                          | Ref: CS/SMR21006287/f3 |                |
| 60 WOODLANDS INDUSTRIAL PARK                                                                                                           |                                                                                          | Date: 01/06/2021       |                |
| E4SINGAPORE 757705                                                                                                                     |                                                                                          | Code: SMR              |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                          |                        |                |
| <b>Insured Veh.</b>                                                                                                                    | SG 5159G                                                                                 | <b>Veh. Inspected</b>  | SLR 9283D      |
| <b>Policy No.</b>                                                                                                                      |                                                                                          | <b>Coverage (\$)</b>   | 0.00           |
| <b>Claim No.</b>                                                                                                                       | BUS/05/21/5040                                                                           | <b>Excess (\$)</b>     | 0.00           |
| <b>Assign From</b>                                                                                                                     | HUA YEN                                                                                  | <b>Assign Date</b>     | 01/06/2021     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                          |                        |                |
| <b>Make &amp; Model</b>                                                                                                                |                                                                                          | <b>c.c</b>             | 0              |
| <b>Engine No.</b>                                                                                                                      | HIDDEN                                                                                   | <b>Year of Reg.</b>    |                |
| <b>Chassis No.</b>                                                                                                                     |                                                                                          | <b>Colour</b>          |                |
| <b>Odometer</b>                                                                                                                        | -                                                                                        | <b>Steering</b>        |                |
| <b>Brakes</b>                                                                                                                          |                                                                                          | <b>Modification</b>    |                |
| <b>General</b>                                                                                                                         |                                                                                          |                        |                |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                          |                        |                |
|                                                                                                                                        | <b>Size</b>                                                                              | <b>Make</b>            | <b>Balance</b> |
| <b>R/H Front Tyre</b>                                                                                                                  |                                                                                          |                        | mm             |
| <b>L/H Front Tyre</b>                                                                                                                  |                                                                                          |                        | mm             |
| <b>R/H Rear Tyre</b>                                                                                                                   |                                                                                          |                        | mm             |
| <b>L/H Rear Tyre</b>                                                                                                                   |                                                                                          |                        | mm             |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                          |                        |                |
|                                                                                                                                        |                                                                                          |                        |                |
| <b>5. General Information</b>                                                                                                          |                                                                                          |                        |                |
| <b>Accident Date</b>                                                                                                                   | 23/05/2021                                                                               | <b>Inspection Date</b> | 01/06/2021     |
| <b>Survey held at</b>                                                                                                                  | CYCLE & CARRIAGE INDUSTRIES PL<br>188 PANDAN LOOP<br>SINGAPORE 128378<br>(MERCEDES-BENZ) |                        |                |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                          |                        |                |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                          |                        |                |