

ASS. REC. BY:

RECS/AG/21008293/Kvf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMR 4363C

Policy No. 2070150926

Claims No. 2913967407SG


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2-4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV 448PY Yr Regn: 12, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota CHR c.c. 1797

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 29209 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 8YX10 - 2088253

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil S/Rlm STD A/Rlm or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 12/5/21

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 1/6/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/6/21 Kenneth confirmed LS \$2650 (Red 4214.95, 61%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 8/6/21-Typist

Days Of Repair: 3

Resurvey No. of Trlp: 2

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format: Merimen

Lump Sum / L.B. (\$2650)

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLV 4469 Y
Make : Toyota C-HR
Year : 2017

*Not Authorised
L1 Sing B
Resurvey After Paint*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy		<i>R</i> \$1,339.60 <i>X</i>
1 pc	Rear n/s tail-gate reflector		<i>Gr</i> \$550.10 <i>✓</i>
1 pc	Rear n/s tail-lamp assy		<i>CVT</i> \$683.20 <i>✓</i>
1 pc	Rear bumper		<i>Bul / CM</i> \$985.10 <i>✓</i>
1 pc	Rear bumper reinforcement		\$483.20 <i>?</i>
1 pc	Rear n/s bumper reflector garnish		<i>nd</i> \$125.60 <i>✓</i>
1 pc	Rear n/s bumper reflector		<i>CM</i> \$95.70 <i>✓</i>
1 pc	Rear lower bumper		<i>CM</i> \$655.70 <i>✓</i>
2 pcs	Rear bumper side retainer	<i>N/S Div</i> \$75.10	\$150.20 <i>✓</i>
2 pcs	Rear fender arch garnish	<i>N/S Bu</i> \$165.20	\$330.40 <i>✓</i>
1 pc	Rear end panel		\$725.70 <i>?</i>
1 pc	Rear end panel inner garnish		<i>Pu</i> \$402.10 <i>X</i>
			\$6,526.60
Less 25 %			\$1,631.65
			\$4,894.95

S Nett

15 pcs	Rear bumper clip	\$2.00	<i>Me</i> \$30.00 <i>✓</i>
1 pc	Rear reverse sensor		<i>Sm</i> \$200.00 <i>X</i>

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$800.00	<i>?</i>
To putty & spray paint on accident affected portion	\$800.00	<i>400</i>
Check and reconnect wiring	\$40.00	<i>200</i>
To anit- rust proofing	\$100.00	<i>?</i>
Total	\$6,864.95	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 14/05/2021 12:06 (SGT)
Date of Accident 12/05/2021 20:31 (SGT)
Exact Location of Accident Near Woodlands Ave 12, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLV4469Y

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner L H Car Rental Pte Ltd
Company Reg No 2XXXXXX761N
Email Address carrental.lh@gmail.com
Mobile Phone No (Phone) +65-97687073
Alternative Phone No (Office) +65-64817221

VEHICLE PARTICULARS

Manufacturer Toyota
Model C-hr
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1797

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number DMHCSNA00004222101
Cover Note Number -

DRIVER

Name of Driver Zhu Jinzong
NRIC No SXXXX038D

SKETCH PLAN

- L.H CAR RENTAL PTE LTD

Witnessed by Reporting Centre
Personnel

Car A = SLV4469
Car B = SMD436
Woodland Ave 12