SV0L21610003 / VICOM LTD (VAC) - Kaki Bukit [415933] ENTRY DATE & TIME: 01/06/2021 14:22 (SGT)
SUBMITTED BY: Siti Fadhlon Abdul Kader
VERSION: 1 (01/06/2021 14:22 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

<u>ACCIDENT STATEMENT</u>

Date of Submission Date of Accident **Exact Location of Accident**

Additional Location Information Country/State of Loss

SLE TWRDS CTE(AFTER SLE(CTE/TPE) ENTRANCE

Singapore

Singapore

01/06/2021 14:22 (SGT)

01/06/2021 09:05 (SGT)

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKK9806U

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner NRIC No

Email Address Mobile Phone No

Alternative Phone No

No

LOH KONG NGAM SXXXX190H

smartoneauto@gmail.com (Phone) +65-97361619 +65-97361619

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Toyota

TOYOTA / COROLLA AXIO 1.5X

Private use

No - Claiming third party

Private car Auto 1498

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number

NTUC Income Insurance Co-operative Ltd

Comprehensive

No

5110297521-01

DRIVER

Name of Driver NRIC No

LOH KONG NGAM SXXXX190H



Date Of Birth 29/08/1945 Occupation Indoor Date Of Driving Pass 30/07/1965

Driving experience 55 YEARS AND 11 MONTHS

Gender

Mobile Number (Phone) +65-97361619

Alt. Phone Number +65-97361619

Email Address smartoneauto@gmail.com

Address BLK 229 #08-141 CHOA CHU KANG CENTRAL

Address complement

Postcode 680229 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED;

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes

Reasons for not uploading a video of the accident WITH OWNER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJP2982A Vehicle Manufacturer Honda

Vehicle Model HONDA / CITY 1.5L I-VTEC AUTO

Vehicle Variant Vehicle Colour

Vehicle Category

Private car Name of Driver

Contact Number Address

Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2 This Fernmust be completed by the Policyholder and/or the Authorised Oriver.
- 3 Information provided must be as truthful and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lundersland, acknowledge, agree and consent that

(a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law (ams, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, declade and/or process my Parsonal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date & Time

IDAC KAN BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Emai, waaki shri maricmisg

Witnessed by Reporting Centre
Personnel 0 1 JUN 2021

Sketch Plan

A= SKK9806U
B= SDP2982A

SLE towards CTE
[After SLE(CTE/TPE) Entrance]

Declaration

TWe declare the foregoing particulars are true in every respect

Polospetroje Sanatura (Polos

Pakcyholder's Signature / Date & Time

AWKI1

Driver's Signature (f driver is not the policyholder) (Oate & Time

DAC KAKIBUKII (VAC) 23 KatiBukit Ave 4 KOT-02 Shigapar 4 15938 Tel 674 16657 Tavi 67402305 Final Soft — Hillotang

Winessed by Reporting Centre Personnel

31 0 201

On 01.06.2021 at about 09:05 hours along SLE towards CTE (After SLE (CTE/TPE) Entrance), I was travelling straight on lane 2 at the above mentioned location.

Suddenly I heard a loud bang and felt an impact from my right side. When I alighted, I realised it was vehicle (B) from lane 1 that cut into my lane (lane 2) hence collided onto the right hand side portion of my vehicle (A).

Winn.

Vehicle (A): SKK 9806U

Vehicle (B): SJP 2982A

Accident report SV0L21610003