ASSIGNMENT

From	Date:	Veh No: SLA 2017S Yr Regn: 2016, Feb	
Estimated Cost:		Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /	
OD/TP/WS/	TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No:		Make: Toyota Fielder- c.c 1496.	
at Workshop m/s		Colour Blue · A/C: Insured / Std / NI / NA	
of		Sp.Reading 64989. T/Radio: Insured / Std / NI / NA	
Inquired:		Eng/No:	
Policy No.		C/No: NR £ 161800067 .	
Claims No.		Gen. Cond Good Fair / Poor / Burnt	
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leaked / Burnt or	
(Client's Reco	ord)	Brake: inorder / Jammed / Leaked / Burnt or	
Make of Veh:		Modi: Nil (S/Rim)/ STD A/Rim or	
		Tyre Size: F: /56/60R/3	
(Policy Condition)		R: 195/60R15.	
Remark: The veh had commenced its N/S O/S		BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /	
repair at the time of inspection.		TOYOTYOKO or Habilead.	
Bal. or Market Value:		Front Rear	
IDAC Accident Rport: Consistent? : Yes or No		R/Bal. 06 mm R/Bal. 06 mm	
GIA / PR Seen: Consistent? : Yes or No		L/Bal. 06 mm	
Est. Repairs:days Res.: Yes or No		D.O.A. D.O.I. 02/06/21.	
Lum Sum: % 3 Val.: Yes or No		Survey held at Ace Autolution!	
CA / REV / REP. / 24 HRS		Des. of Damages : Frt / Rear / O/S (N/S) / U/C / Rooftop or	
Vehicle: IN / OUT Date: Person Contacted:		The U/C / Chassis frame / Body Structure affected due to collision.	
Date / Time Action / Instruction		The ord / Ghassis frame / Body structure and the	
Date / Time	Ti2 AIG.	,	
	1	Nepter Co. 4 is	
	M ∨ :		
	PV:		
	Nett:	ν.	
		- 10 (MBH) 1 (MBH)	
	Formal	David Of Baselin	
Date/Time, File Pa		Days Of Repair: Resurvey No. of Trip: Survey Fee:	
Final Report Date/Time, File Return to?		Resurvey No. of Trip: Survey Fee: Transportation:	
Add Fee			
2)		: Interview (\$) Photos	
Report Format :		: Tech Invs (8) others	
		The second secon	
Long Sum / LBJ: C: : Weetend (S)			