



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006309/T1uf3n2	
			Date: 04/08/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1332X	Veh. Inspected	XE 5134D
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/12/20/1026	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	01/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	SCANIA P410B6X4HZ	c.c	12742
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	YS2P6X40005520139	Colour	MAROON
	Odometer	120630 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/30 R22.5	TRIANGLE	8 mm
	L/H Front Tyre	295/30 R22.5	TRIANGLE	8 mm
	R/H Rear Tyre	295/30 R22.5 (D)	TRIANGLE	8/8 mm
	L/H Rear Tyre	295/30 R22.5 (D)	TRIANGLE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/12/2020	Inspection Date	03/06/2021
	Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	