

A.S.S. REC. BY: Toughlin

REF:

104/ALG 21006311/Tigs 3

ASSIGNMENT

2022 Aug.

2022, Aug.

From: _____

Date: _____

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 53K952K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFD3663A

Yr Regn: _____

Type: (M) Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes BenzE250

c.c

179LColour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 138968

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2120472 A 63 2086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: NII / S/Rim / STD A/Rim or _____

Tyre Size: F: 245/35 R19R: 2BS / (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 24/21 05pmSurvey held at AP Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format: _____

Lump Sum / L.B. / C: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	888D

Vehicle Details

Vehicle No.:	SFD3663A
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jun 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	27186030483504
Chassis No.:	WDD2120472A632086
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$54,005.00
Original Registration Date:	23 Aug 2012
First Registration Date:	23 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$54,005.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Aug 2022
PARF Rebate Amount:	\$29,702.00

Intended COE Rebate Details

COE Expiry Date:	22 Aug 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$94,502.00
COE Rebate Amount:	\$10,796.00
Total Rebate Amount:	\$40,498.00

The information contained herein is correct as at 31 May 2021

OK