

ASS. REC. BY: Taufikh

REF: CS/EG121006314/Tiqf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 5386G

at Workshop m/s EM-1 AUTO

of _____

Insured: GBK 6548R

Policy No. _____

Claims No. CDMCG21001000

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$50K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: MT Clm'n

Vehicle: IN / OUT

Veh No: SLA5386G Yr Regn: 2016, March

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Nissan Sylphy C.C. 1598

Colour: Silver A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 122547 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: MNTBBABI720026657

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 195/60R16

R: _____

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 2/6/21 24pm

Survey held at EM-1 Auto

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

7/6/2021 @ 4.08pm Revise to ERGO via Merimen.

8/07/21 @ 2.36pm Taufikh finalised with Karen LS \$3300, 4 days. (Red \$2482.50, 43%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 28/07 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: MER-TP

Lump Sum / 12.11.21 3300

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

Photos

Others

TOTAL

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLA 5386G
Vehicle Model : NISSAN SYLPHY
Accident Date : 23.05.2021
Original Reg Date : 02.03.2016

Date : 02.06.2021
Chassis : MNTBBAB17Z0026657
TP Ins. **ERGO**

ESTIMATE

1	1 pc	Front Bumper	de ✓			N
2	1 pc	Front Bumper Reinforcement	ht ✓			N
3	1 set	Front Bumper Sponge	cut ✓			N
4	2 pcs	Front Bumper Side Retainer	LH x, RH ne ✓			N
5	1 pc	Front Bumper Clip	ne ✓			N
6	1 pcs	Front Bumper Fog Lamp Cover	RH. cut ✓			N
7	1 pc	Head Lamp RH	cut ✓			N
8	1 pc	Head Lamp Bottom Retainer RH	de ✓			N
9	1 pc	Front Fender RH	ht ✓			N
10	1 pc	Front Fender Inner Shield RH	de ✓			N
11	1 set	Front Fender Inner Shield Clip RH	de ✓			N
12	1 pc	Wiper Tank	de ✓			N

Special Nett

1	1 pc	Front Sport Rim RH	cut ✓		500.00
---	------	--------------------	-------	--	--------

Labour charge

Panel Beating		450.	800.00
Spray painting		450.	800.00
Check Wiring		30.	30.00
Anti rust		30.	50.00
To perform Computerize wheel alignment.		80.	90.00

Tanpin 97495745
WP' 26/7/21 04pm
c/s Resurvey after repair
04 days
Tanpin 1/June/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	721C
Vehicle Details	
Vehicle No.:	SLA5386G
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2021
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	HR16983678B
Chassis No.:	MNTBBAB17Z0026657
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,283.00
Original Registration Date:	02 Mar 2016
First Registration Date:	02 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$16,283.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Mar 2026
PARF Rebate Amount:	\$11,398.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$20,487.00
Total Rebate Amount:	\$31,885.00

The information contained herein is correct as at 24 May 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/05/2021 15:07 (SGT)
Date of Accident	23/05/2021 16:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG YISHUN RING ROAD CARPARK, BLK 615
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA5386G
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN KENG LIAN
NRIC No	SXXXX721C
Email Address	washerahyee@gmail.com
Mobile Phone No	(Phone) +65-96605452
Alternative Phone No	+65-96605452

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Sylphy
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5116030379-01
Cover Note Number	-

DRIVER

Name of Driver	TAN KENG LIAN
NRIC No	SXXXX721C

Date Of Birth	22/06/1961
Occupation	Outdoor
Date Of Driving Pass	31/10/1980
Driving experience	40 YEARS AND 7 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96605452
Alt. Phone Number	+65-96605452
Email Address	washerahyee@gmail.com
Address	BLK 704 HOUGANG AVE 2 #01-209
Address complement	-
Postcode	530704
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK6548R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	WONG PEK YEW
NRIC No	SXXXX159F
Contact Number	-
Address	-

Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

BIK 615	
My vehicle was park at Yishun Ring Rd Carpark	
Lot No 60 around 15.30pm waiting for my worker.	
I heard a loud bang then I walked toward my	
vehicle and I saw a damage on my right hand	
portion. About 10 mins later, vehicle B driver return back	
to the scene and give me a written black & white	
admit fault letter. He advise me to proceed to report	
insurance and claim under his insurance policy	
J. M.	
Vehicle A : 3LA 5386A	
Vehicle B : GBK 6548R	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

CITY AUTO PTE LTD
Blk 8 Seng Guan Road
#01-58/60/62 Seng Guan Ind Est
Singapore 575843
Tel: 6453 1235 | Fax: 6453 7944
(Claims Section)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Hi Sorry for a delivery man
I hit your car in front, my car
number GBK6548R, My contact number
Andy 87803512 Sorry

SLA53SE - Andy

Typo