

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 01/06/2021 16:40 (SGT)
Date of Accident 11/05/2021 06:35 (SGT)
Exact Location of Accident Yio Chu Kang Rd, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number CB7774H

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner DYNACLE TRANSPORTATION AND WORKSHOP PTE LTD
Company Reg No 2XXXXX894G
Email Address fred.chua@dynacle.com.sg
Mobile Phone No (Phone) +65-81682419
Alternative Phone No +65-81682419

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model BE639JRMHDEA
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only
Vehicle Category Bus
Transmission Manual
CC 3908

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage ThirdPartyFireTheft
Fleet Policy No
Policy Number DMB1SNA00007262000
Cover Note Number -

DRIVER

Name of Driver TAN PENG HWEE
NRIC No SXXXX206J

Date Of Birth	28/12/1961
Occupation	Outdoor
Date Of Driving Pass	19/05/1992
Driving experience	29 YEARS
Gender	Male
Mobile Number	(Phone) +65-81682419
Alt. Phone Number	-
Email Address	fred.chua@dynacle.com.sg
Address	BLK 911 HOUGANG STREET 91 #06-62
Address complement	-
Postcode	530911
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	16
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Female

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Female

PASSENGER 4

Name	UNKNOWN
Gender	Female

PASSENGER 5

Name	UNKNOWN
Gender	Female

PASSENGER 6

Name	UNKNOWN
Gender	Female

PASSENGER 7

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Hougang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004890999
Alt. Police Station Phone No	(Fax) +65-63128989
Police Station Address	60 Hougang Ave 9 Singapore 538775
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT T/20210511/2012

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH OWNER
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU8383P
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKW7641C
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	UNKNOWN PAX
Address	-
Address Complement	-

Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	CB7774H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 2

Name of injured person	UNKNOWN PAX
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	CB7774H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 3

Name of injured person	UNKNOWN PAX
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	CB7774H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A= CB7774 H
B= SL48383P
C= SKW7641C.

yio chu kang rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

* P19 ref to police report *. T/20210511/2012

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:













CHASSIS NO	:	BE639JD00370	<input type="checkbox"/>
UNLADEN WT	:	3780	KG
MAX LADEN WT	:	6100	KG
PASSENGER CAP	:	1 DRIVER	23 OTHER
TYRE SIZE	:	(F) 205-80R-17.5	
	:	(R) 205-80R-17.5(D)	







SINGAPORE POLICE FORCE		T/20210511/2012				
Police Station Of Origin: Hougang N.P.C. 60 Hougang Avenue 9 SINGAPORE 538775 Tel No. 1800 4890899		1 of 4 Report No. T/20210511/2012				
REPORT OF A TRAFFIC ACCIDENT						
Date/Time Report Made 11/05/2021 11:00		Vide Report No. P/20210511/0042				
		Station Diary No. 26				
Informant's Particulars						
Name of Informant TAN PENG HWEE		Address: APT BLK 911 HOUGANG STREET 91 #06-62 SINGAPORE 530911				
ID Type / ID No. NRIC NO / S1467206J		Contact No. Home/Office: Mobile: 91014658				
Nationality SINGAPORE CITIZEN		Email:				
Sex Male	Age 59	Date of Birth: 28/12/1961	Type of Informant: Driver			
Race Chinese	Language: Chinese		Institution / School Name			
Occupation Bus driver	Driving Licence Information: Class: 2B,3,4,5		Date of Expiry:			
General Information of the Accident						
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/05/2021 06:35			
Type of Location:						
YIO CHU KANG ROAD						
Weather: Clear	Road Surface: Dry	Road Speed Limit				
Traffic Flow: Two Way	Traffic Control:	Traffic Volume: Heavy				
Type of Collision: Head to rear (Chain collision)		Anyone conveyed by ambulance: Yes				
Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CB7774H	Bus/Coach/Minibus (School Children)	MITSUBISHI		White	Slightly Damaged	14
SKW7641C	Car	TOYOTA		Silver	Slightly Damaged	1
SLU8383P	Car	MERCEDES BENZ		Black	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20210511/2012

Police Station Of Origin
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 4

Report No: T/20210511/2012

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN PENG HWEE	ID No.	S1467206J
Related Vehicle	CB7774H (Bus/Coach/Minibus (School Children))	Contact No.	91014558
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B, 3, 4, 5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/05/2021 at about 0638hrs, I was driving my company bus CB7774H along Yio Chu Kang Road towards the slip road of Central Expressway (CTE). I was driving at the middle lane. I signalled to my left. After which, I changed to the left lane.

After I changed to the left lane, suddenly a silver Toyota Estima SKW7641C jam brake. A black Mercedes SLU8383P collided on the silver Toyota Estima as the driver of black Mercedes could not react on time. After which, I applied brake. However my company bus collided on the black Mercedes as I could not react on time.

After the collision, I went to make a check on my passengers in my bus. There are 3 passengers informed that they were in pain. After which, I alighted from my company bus to make a check.

The driver of the silver Toyota Estima and black Mercedes also alighted from their vehicle to make a check. The driver of the silver Toyota Estima informed that her passengers and herself are fine.

The driver of the black Mercedes informed that he felt giddy and pain on this shoulder.

The driver of the black Mercedes then called for ambulance.

Shortly awhile, ambulance and traffic police arrived. The ambulance then conveyed 3 of my passengers and the driver of the black Mercedes to the hospital.

The silver Toyota Estima sustained a huge inward dent on its rear boot door. The black Mercedes sustained damages on the rear boot, rear bumper and rear headlights.

My company bus sustained a inward dent on the front bumper and a damaged front right headlights. The driver's door is damaged due to the impact of the collision.

There are 2 in-car cameras inside my company bus that captures the front and in-vehicle view and 2 in-car cameras on top of my company bus that is installed on the front of my company bus. The 2 in-car cameras on top of my company bus captured the rear view.



SINGAPORE POLICE FORCE



Police Station Of Origin
Hougang N P C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 KELVIN TAN KIM HENG *Kelvin*

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt MOHAMED SUFIAN BIN MOHAMED
JUNID

Contact No: 65476247
Authenticating Stamp
NP168

Kelvin
SIGNATURE

Signature Of Informant
[Signature]

Date/Time
11/05/2021 11:00

Classification Of Case