



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III21003423/Gqce2-1	
			Date: 15/06/2021	
			Code: III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHC 8141M	Veh. Inspected	FBF 937M
	Policy No.	MCOM0015	Coverage (\$)	0.00
	Claim No.	MCT20070055	Excess (\$)	0.00
	Assign From		Assign Date	02/06/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA X-1R	c.c	135
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	4S3303000	Colour	GREY
	Odometer	89072 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	PIRELLI	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90-17	PIRELLI	4 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/07/2020	Inspection Date	16/03/2021
	Survey held at	PROJECT 8 MOTORWORKS 61 WOODLANDS INDUSTRIAL PARK E9, #01-03, E9 PREMIUM, SINGAPORE 757047		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	