

ASS. REC. BY:

Steve

CS/CTI21006333/Eqc

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 5955U

at Workshop m/s

of

Insured:

GBE 7280L

Policy No.

DMCVSNW00026302100

Claims No.

SNM21D203125/C02

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLS 5955U

Yr Regn:

28/9/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 530i

c.b.

1998

Colour:

White

A/C: Insured / Std / NI / N

Sp. Reading

75550

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

WBAJA 520X01C97536

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or *Cinturato*

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

30/5/21

D.O.I.

22/6/21

Survey held at

Performance Motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear LH

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

REV - 162K

22/6/2021 @ 4.10pm Revise to CTI via Merimen.

Date/Time, File, Pass w/

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (%)

☐

: Weekend (%)

\$ + RS \$

Photos

Others

TOTAL

Approved/Forward:

Date/Time/Signature:

Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 58579  
Date Estimated : 02/06/2021  
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Yap Wei Ling (Ye HuiLing)  
384 Bukit Batok West Avenue 5  
#08-326

Singapore 650384

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS5955U	WBAJA520X0WC07536	28/09/2017	530i	73241

### DESCRIPTION

To replace rear left door, left side skirt, rework left rear side panel and left c pillar

2.5 x 850

2125. 4,250.00

To respray left rear door, left side skirt, left rear side panel

2466 2,596.00

To replace tyre and wheel rim including balancing. (1x).

90 94.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

504 531.00

To conduct check on all doors and central locking system for proper function.

168 177.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

To carry out body cavity preservation. (Per panel).

112 118.00

Sundries.

150.00

Total Labour 1: 8,093.00

### DESCRIPTION

EXPANDING RIVET / APC  
ALLOY RIM FERRICGREY 9JX19 SPK 663 / CUT  
REAR LH DOOR ALUMINIUM / APC  
RR LH DOOR SIDE WINDOW FIXED GREEN ?  
(S/L) DOOR WEATHERSTRIP / APC  
LH SUPPORTING LEDGE ?  
LH SILL TRIM PRIMED X R

QTY	PRIC	VALUE
16	0.90	14.40
1	1,595.80	1,595.80
1	1,881.90	1,881.90
1	425.15	425.15
1	175.65	175.65
1	21.40	21.40
1	427.25	427.25

Total Parts : 4,541.55

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 58579  
Date Estimated : 02/06/2021  
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS5955U	WBAJA520X0WC07536	28/09/2017	530i	73241

Steve CLKK) WML PL  
22/6/21, 10:30am 6 dys  
Ry BL sy  
P/P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



Labour 1	:	8,093.00
Parts	:	4,541.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	884.42
Grand Total	:	13,518.97

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	31/05/2021 11:49 (SGT)
Date of Accident	30/05/2021 10:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BLK 395 BUKIT BATOK WEST AVENUE 5 MSCP
Country/State of Loss	Singapore

### OWNERS OF OWN VEHICLE

Vehicle Registration Number	SLS5955U
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	YAP WEI LING
NRIC No	S7727226G
Email Address	Yapweiling@yahoo.com
Mobile Phone No	(Phone) +65-96817388
Alternative Phone No	+65-96817388

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	530i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5118849205
Cover Note Number	-

### DRIVER

Name of Driver	TAN CHOON HOCK
NRIC No	S7508908B

Date Of Birth	20/03/1975
Occupation	Indoor
Date Of Driving Pass	05/06/1998
Driving experience	22 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91860391
Alt. Phone Number	-
Email Address	Choon_hock.tan@yahoo.com
Address	3 WEST COAST DRIVE #11-01 NEWEST
Address complement	-
Postcode	128021
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	EMAIL TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	GBE7280L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	LIM CHOON NAM
NRIC No	S7219022Z
Contact Number	-

Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-  
-  
1

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 21/05/2024 11:43:02

Reporting Centre Personnel's Signature  
Name: ACHAND JEFAYAN  
NRIC/FIN No.: J6705749A



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/05/2021 at around 1050hrs, I was driving straight in the carpark when Veh B: GBE 7280L turn in from the carpark entrance and hit into my left rear left side of vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 31/05/2021 1145hrs

Reporting Centre Personnel's Signature  
Name: A. S. S. S.  
NRIC/FIN No.: 887051744