



Your Ref: S1M035C0

Date: 14<sup>th</sup> June 2021

Our Ref: CS3/ASM21002315/Gvce2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Yu Dominic Yishan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLM 9011Z**

**INSURED VEHICLE: SH 6136K**

**ACCIDENT DATE: 16/12/2021**

We thank you for your instruction on 02/06/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLM 9011Z from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement of Vehicles SLM 9011Z and SH 6136K.
- c) Police Report of Vehicles SLM 9011Z.
- d) Final Repair Bill of SLM 9011Z from M/s Eclipse Auto Pte Ltd.
- e) Colour damaged vehicle photographs of SLM 9011Z.

Pre-Repair Inspection Date : 18/02/2021 at M/s Eclipse Auto Pte Ltd, 155 Kaki Bukit Avenue 1 #01-00 Shun Li Industrial Park, Singapore 416012.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLM 9011Z
Make & Model	: Volkswagen Jetta 1.4 TSI A/T ABS D/Airbag 2WD
Year of Registration	: 2015
Chassis Number	: WVWZZZ16ZEM059053
Engine Capacity	: 1390 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.