

ASS. FILE BY

bml
PRS

AXA

ASSIGNMENT

From

Date

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured: SH 6136K

Policy No.

Claims No. S1M0337K

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days

Res.: Yes or No

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SLM90118

or Regn

30 Jan 2015

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Jetta 1.4 1390

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

175783

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WUW228162EM059053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A. 16/2/21

D.O.I.

18-02-21

Survey held at

W/S

5:10pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S TA

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

006: 31600

~~\$4000~~ \$5000 - \$6000

11/6/21 Submit LS \$4500 (Red 4700,51%)

14/6/21 Amend LS \$4800 (Red 4400,47%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Misc. Insp (\$

Survey Fee:

Transportation:

3 + RS \$

Photos

Other

19/2/21 Typist

11/6/21-Typist

Report Printed: PRS TP

Report Sum / LS 4800