



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883 ON BEHALF OF ABDUL RAHMAN BIN RAHIM THOOLLAH			Ref: CS/TP21006369/Uqf3e2 Date: 21/06/2021 Code: TP510	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SJK 1007Z	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	03/06/2021	
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VELLFIRE ELEGANCE (A)	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTNGF3DH108018678	Colour	BLACK
	Odometer	40645 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45Z R19	FALKEN	7 mm
	L/H Front Tyre	245/45Z R19	FALKEN	7 mm
	R/H Rear Tyre	245/45Z R19	FALKEN	7 mm
	L/H Rear Tyre	245/45Z R19	FALKEN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/06/2021	Inspection Date	03/06/2021
	Survey held at	CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	