

ASS. REC. BY:

REF:

AIG/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$11K

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 10/22 Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGY 6547K Yr Regn: 10, 07Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or SAMake: Pur PX4 c.c. 1586Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 271999 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: TSAGYC21S00 100913Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 3 mmL/Bal. 7 mm L/Bal. 3 mmD.O.A. 2/6/21 D.O.I. 3/6/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

1

7/10/22

UNECONOMICAL TO REPAIR

LESS

MARKET VALUE: \$11,000.00

LTA REBATE: \$5,626.00

NETT VALUE: \$5,374.00

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S - RS. \$

), Fuel

), Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I. (\$ \_\_\_\_\_)



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Owner ID:

### Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count: COE Rebate For Registered Vehicle

Actual ARF Paid:

### Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

### Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jun 2021

Singapore NRIC  
539C

SGY6547K

Yes

10 Jun 2021

SUZUKI

SX4 1.6NB AT

Silver

2007

M16A1286924

JSAGYC21500100193

75.0 kW (100 bhp)

\$12,453.00

04 Oct 2007

04 Oct 2007

1

\$13,699.00

Forfeited

-

\$0.00

03 Oct 2022

A - Car (1600cc & below)

5

\$21,282.00

\$5,591.00

\$5,591.00

OK