

(08/11/13) wef
ASS. REC. BY: *Pam*

REF:

CS/GRB21006378/Riqf3

2009

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMM 6425X*

at Workshop m/s *PERKINS*

of *74, KIAN TEAK RD*

Insured: *111*

Policy No. *D21MFL0000447*

Claims No.

Sum Insured:


Excess: *TBA*

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *113K*

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: *SMM 6425X*

Yr Regn: *2019 / July*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *HYUNDAI*

OS KONA EV

c.c. *-*

Colour: *GREY*

A/C: *Insured / Std / NI / NA*

Sp. Reading: *-*

T/Radio: *Insured / Std / NI / NA*

Eng/No:

C/No: *KMHK2816UKU030423*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F: *215/55ZR17*

R: *-*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal. *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *02/06/21*

D.O.I. *04/06/21*

Survey held at *PERKINS*

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 62K

07/06/21@3.39pm revert to Priya via Merimen.

08/06/21@9.40am Priya informed that "we will not claim under OD and revert as RO only".

08/06/21 Submit Preli. report. - WE HAVE NOT AUTHORISE REPAIR.

Date/Time, File Pass to?



Preli. Report

1) 08/06 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: *10*

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS, SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format : *MER-OD*

Lump Sum / I.B.I: (\$

)

TOTAL



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn: : Tel : Fax No. :

Quotation No. : QO21/06-1022	Quotation Date : 03/06/2021	Terms : 60 DAYS
Vehicle No. : SMM6425X	Chassis No. : KMHK281GÜKU030423	Policy Number :
Model : HYUNDAI KONA		Date of Accident : 03/06/2021
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	MODULE ASSY-AIR BAG CONTROL <i>Act /</i>	1	276.2700	276.27
2	AIR GUARD <i>cm /</i>	1	24.9000	24.90
3	BUZZER ASSY-PIEZO <i>cm /</i>	1	31.4300	31.43
4	WIRING ASSY-COMBO CHARGER <i>cm /</i>	1	569.6100	569.61
5	BLOWER ASSY ?	1	253.3800	253.38
6	BONNET <i>bt /</i>	1	488.0900	488.09
7	BONNET LOCK <i>bt /</i>	1	36.1100	36.11
8	MODULE-CHARGE DOOR <i>sc /</i>	1	435.8400	435.84
9	AIR CON CONDENSER <i>bt /</i>	1	332.6600	332.66
10	EPCU ASSY ?	1	4,590.7400	4,590.74
11	COVER ASSY-COWL TOP <i>sc / cm /</i>	1	51.8600	51.86
12	FRONT BUMPER CTR MOULDING <i>sc /</i>	1	51.0000	51.00
13	PANEL ASSY-C/PAD UPR PASS SIDE ?	1	145.0100	145.01
14	MODULE ASSY-STRG WHEEL AIR BAG <i>Act /</i>	1	607.1300	607.13
15	BRACKET-MOTOR MTG SUPPORT ?	1	132.7700	132.77
16	TANK ASSY-RESERVOIR <i>de /</i>	1	37.7300	37.73
17	FRONT BUMPER LOWER COVER X SVC	1	155.1900	155.19
18	BRACKET-LOGO MTG <i>cm /</i>	1	8.4800	8.48
19	FRONT BUMPER <i>turn /</i>	1	176.6600	176.66
20	TRACTION MOTOR ASSY ?	1	8,406.4800	8,406.48
21	CARRIER ASSY-FRONT END MODULE <i>cm /</i>	1	187.8300	187.83
22	CROSSMEMBER COMPL	1	291.5900	384,041.48
23	BEAM COMPLETE-FRONT BUMPER <i>bt /</i>	1	302.2400	302.24

C/F

0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Officer in Charge : VIVIAN TAN EE WI Tel : Email :	Attn : Tel : Fax No. :

Quotation No. : QO21/06-1022	Quotation Date : 03/06/2021	Terms : 60 DAYS
Vehicle No. : SMM6425X	Chassis No. : KMHK281GUKU030423	Policy Number :
Model : HYUNDAI KONA		Date of Accident : 03/06/2021
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	CAP-TOWING HOOK <i>scr</i> ✓	1	1.0700	1.07
25	WIRING HARNESS-FRONT BUMPER <i>X</i> SVC	1	79.6800	79.68
26	BRACKET-REINF ?	1	12.6900	12.69
27	ABSORBER-FRONT BUMPER ENERGY <i>cm</i> ✓	1	12.4700	12.47
28	MOULDING-FRT BPR LICENSE PLATE <i>cm</i> ✓	1	7.2200	7.22
29	GEAR DRIVE UNIT ASSY ?	1	1,673.8700	1,673.87
30	EMBLEM-SYMBOL MARK <i>nu</i> ✓	1	6.8600	6.86
31	CRASH PAD ASSY-MAIN ?	1	387.9200	387.92
32	HINGE ASSY-HOOD (LHS) <i>X</i> SVC	1	10.9100	10.91
33	PIECE-FRT BUMPER GUARD LWR (LHS) <i>nu</i> ✓	1	15.0600	15.06
34	SHAFT ASSY-DRIVE (LHS) ?	1	319.5200	319.52
35	BRACKET ASSY-FRT BUMPER SD UPR ?	1	4.2600	4.26
36	S/BELT ASSY-FR (LHS) <i>act</i> ✓	1	328.1600	328.16
37	SENSOR ASSY-A TYPE CRASH ?	1	26.6000	26.60
38	S/BELT ASSY-RR (LHS) <i>act</i> ✓	1	237.9000	237.90
39	LAMP ASSY-HEAD (LHS) <i>bro</i> ✓	1	247.2500	247.25
40	PANEL ASSY-UNDER COVER FRONT ?	1	37.5300	37.53
41	AIR BAG ASSY-PASSENGER <i>act</i> ✓	1	686.1900	686.19
42	HINGE ASSY-HOOD (RHS) <i>act</i> ✓	1	10.9100	10.91
43	SHAFT ASSY-DRIVE (RHS) ?	1	319.5200	319.52
44	BRACKET ASSY-FRT BUMPER SD UPR <i>nu</i> ✓	1	4.2600	4.26
45	S/BELT ASSY -FRT (RHS) <i>act</i> ✓	1	328.1600	328.16

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : VIVIAN TAN EE WI
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO21/06-1022	Quotation Date : 03/06/2021	Terms : 60 DAYS
Vehicle No. : SMM6425X	Chassis No. : KMHK281GUKU030423	Policy Number :
Model : HYUNDAI KONA		Date of Accident : 03/06/2021
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	SENSOR ASSY-A TYPE CRASH ?	1	26.6000	26.60
47	MEMBER ASSY-FRONT SIDE (RHS) X SVC	1	256.7600	256.76
48	BRACKET ASSY-CARRIER MTG (RHS) X SVC	1	6.9800	6.98
49	LAMP ASSY-DAY RUNNING LIGHT (RHS) cm ✓	1	193.4400	193.44
50	S/BELT ASSY-RR (RHS) ACT ✓	1	237.6300	237.63
51	RADIATOR ASSY bt ✓	1	262.9500	262.95
52	LAMP ASSY-HEAD (RHS) Z ?	1	247.2500	247.25
53	STOPPER-RR WINDOW GLASS X SVC	1	1.5600	1.56
54	CONTACT ASSY-CLOCK SPRING ?	1	58.5800	58.58
55	COVER ASSY-RADIATOR GRILLE UPR cm ✓	1	16.7000	16.70
56	RESERVOIR ASSY-W/SHLD WASHER X SVC	1	24.8400	24.84
57	GLASS-WINDSHIELD cm ✓	1	568.3800	568.38
58	MOULDING-WINDSHIELD GLASS cm ✓	1	14.4200	14.42
59	BRACKET-MOTOR MTG SUPPORT ?	1	132.7700	132.77
60	BRACKET ASSY-RR MTG ?	1	48.3500	48.35
61	BRACKET ASSY-DECELERATOR MTG ?	1	54.1200	54.12
62	BRACKET ASSY-CARRIER MTG (RHS) X SVC	1	6.9800	6.98
63	BUSHING-CROSSMEMBER MTG ?	1	18.5400	18.54
64	BUSHING-CROSSMEMBER MTG ?	1	14.1600	14.16
65	BUSHING-CROSSMEMBER MTG ?	1	14.1600	14.16
66	BRACKET ASSY-CARRIER MTG (RHS) ? X SVC	1	6.9800	6.98
67	FLAP & DUCT ASSY cm ✓	1	420.0000	420.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : VIVIAN TAN EE WI Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax No. :

Quotation No. : QO21/06-1022	Quotation Date : 03/06/2021	Terms : 60 DAYS
Vehicle No. : SMM6425X	Chassis No. : KMHK281GUKU030423	Policy Number :
Model : HYUNDAI KONA	Date of Accident : 03/06/2021	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
68	PIPE-SUCTON & LIQUID(SHORT) ?	1	225.0000	225.00
69	CABLE-L.D.C POS ?	1	938.0000	938.00
70	CABLE-L.D.C NEG ?	1	71.0000	71.00
71	BUMPER LOWER STIFFNER-FRT <i>bt</i>	1	120.0000	120.00
72	FENDER-FRT LH <i>repair</i>	1	598.0000	598.00
73	FENDER-FRT RH <i>repair</i>	1	598.0000	598.00
74	FRT CHASSIS (WAITING FOR THE PRICE) <i>repair</i> ?	1		
75	FRT LH WHEEL HOUSE PANEL - REPAIR	1		
76	VESS CONTROL UNIT-FRT ?	1	700.0000	700.00
77	FRT RH WHEEL HOUSE PANEL - REPAIR	1		
78	INLET 3 WAY VALVE ?	1	760.0000	760.00
79	MARK UP 10%	1	3,011.8200	3,011.82
80	ERP STICKER <i>nm</i>	1	12.0000	12.00
81	IU BRACKET <i>nm</i>	1	15.0000	15.00
82	PHV DECAL <i>nm</i>	1	20.0000	20.00
83	FRONT NUMBER PLATE AND CASING <i>nm</i>	1	40.0000	40.00
84	FRONT WINDSCREEN GLASS SEALANT <i>nm</i>	1	40.0000	40.00
85	COOLANT <i>nm</i>	1	25.0000	25.00
86	TOWING FEE <i>nm</i>	1	60.0000	60.00
87	TO CONNECT & DISCONNECT ELECTRICAL POWER.	1	250.0000	250.00
88	TO REMOVE AND REPLACE RADIATOR INCLUDING REFILLNG COOLANT	1	120.0000	120.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO21/06-1022	Quotation Date : 03/06/2021	Terms : 60 DAYS
Vehicle No. : SMM6425X	Chassis No. : KMHK281GUKU030423	Policy Number :
Model : HYUNDAI KONA	Date of Accident : 03/06/2021	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
89	TO REMOVE AND REFIX AIR COND CONDENSOR INCLUDING TOP UP AIR COND GAS	1	200.0000	100 200.00
90	TO REMOVE & REFOCUS FRONT HEADLAMP.	1	80.0000	30 80.00
91	TO CHECK STEERING GEOMETRY & CONDUCT COMPUTER WHEEL ALIGNMENT.	1	120.0000	X 120.00
92	TO MOUNT VEHICLE ONTO WORK BENCH TO CARRIAGE MANUFACTURE SPECIFICATION.	1	250.0000	150? 250.00 photo
93	TO REMOVE & REPLACED FRONT WINDSCREEN GLASS & SEND FOR PHV DECAL STICKER.	1	150.0000	120 150.00
94	TO REMOVE & REPLACED DRIVER & PASSANGER AIR BAG, SRS & DASHBOARD.	1	450.0000	200 450.00
95	TO HOIST OUT ENGINE IN ORDER TO FACILITATE REPAIR TO FRONT CHASSIS & REFIT BACK ENGINE BAY. TO WIRING CHECK & RECTIFY WHERE NECESSARY INCLUDING REPLACING ENGINE WIRING HARNESS.	1	680.0000	250? 680.00 photo
96	TO REMOVE & REFIT CAR SEAT AND REPLACED SEAT BELT.	1	250.0000	200 250.00
97	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT ON THE REPLACED PARTS.	1	200.0000	40 200.00
98	TO PERFORM SRS SYSTEM CHECK INCLUDING DIAGNOSTIC & CLEARING FAULT CODES.	1	250.0000	200 250.00
99	TO REMOVE OUT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY.	1	2,000.0000	800 2,000.00
100	TO PUTTY & SPRAY PAINT ON THE FRONT BONNET, FRONT BUMPER, BOTH FRONT FENDER, BOTH FRONT DOOR & LHS REAR DOOR.	1	1,300.0000	1000 1,300.00 X



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	--

Quotation No. : QO21/06-1022	Quotation Date : 03/06/2021	Terms : 60 DAYS
Vehicle No. : SMM6425X	Chassis No. : KMHK281GUKU030423	Policy Number :
Model : HYUNDAI KONA	Date of Accident : 03/06/2021	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
10 days
P/P
Excess: TBA
REVERT
Resurvey before paint

38404.48

Sub Total	38,510.00
GST(7.00%)	2,696.19
Total (SGD)	41,206.19

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/06/2021 18:38 (SGT)
Date of Accident 02/06/2021 16:35 (SGT)
Exact Location of Accident Tampines Ave 5, Singapore
Additional Location Information JUNCTION TAMPINES AVENUE 6
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMM6425X

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner GRAB RENTALS PTE LTD
Company Reg No 2XXXXX200G
Email Address gr.sg.accident@grab.com
Mobile Phone No (Phone) +65-91122131
Alternative Phone No (Office) +65-66550005

VEHICLE PARTICULARS

Manufacturer Hyundai
Model OS KONA EV
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only
Vehicle Category Private hire
Transmission Auto
CC 1600

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number D21MFL0000447
Cover Note Number -

DRIVER

Name of Driver LEE KAH YEUNG
NRIC No SXXXX369D

Date Of Birth	30/05/1975
Occupation	Outdoor
Date Of Driving Pass	29/12/1994
Driving experience	26 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91122131
Alt. Phone Number	-
Email Address	beyoin@gmail.com
Address	BLK 224A SUMANG LANE #17-143
Address complement	-
Postcode	821224
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 2/6/2021 @1635HRS, I WAS TRAVELLING IN MY CAR (VEHICLE A) WITH 2 PASSENGER (1 MALE + 1 FEMALE) ON BOUND. AT THAT POINT OF ACCIDENT I WAS TRAVELLING IN LANE 3. THERE WAS A CAR (VEHICLE B) TRAVELLING INFRONT OF ME, HOWEVER AT THE JUNCTION OF TAMPINES AVENUE 5 AND TAMPINES AVENUE 6 HE SUDDENLY JAMMED HIS BRAKE. I DID NOT MANAGED TO STOP IN TIME. THEREFORE I COLLIDED INTO THE REAR OF HIS CAR. MY FEMALE PASSENGER WAS SLIGHTLY INJURED. HOWEVER, BEFORE THE AMBULANCE CAME SHE AND THE MALE PASSENGER WAS BROUGHT TO A CAR BY TWO CHINESE MAN AND LEFT THE SCENE. THAT'S ALL.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMW1145J
Vehicle Manufacturer	BMW
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
NRIC No	CHENG JUN HONG, PAUL
Contact Number	SXXXX908B
Address	(Phone) +65-84986826
Address complement	BLK 437 TAMPINES STREET 43 #06-135
Postcode	-
Insurance Company Name	520437
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	PASSENGER
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	INJURED
Injured person in which vehicle?	SMM6425X
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 2/6/21 @ 1635hrs, I was travelling in my car (Veh A) with 2 passengers (1 male + 1 Female) on board. At that point of accident I was travelling in lane 3. There was a car (Veh B) travelling in front of me, however at the junction of Temposne Ave S and Temposne Ave E He suddenly jammed on his brake. I did not manage to stop in time. therefore I collided into the rear of his car.
My Female passenger was slightly injured. However before the ambulance came. She and the male passenger was brought to a car by two Chinese man and left the scene that's all

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time
2/6/21 @ 1740hrs

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SMM6425X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jun 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	OS KONA EV
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	-
Chassis No.:	KMHK281GUKU030423
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$39,758.00
Original Registration Date:	08 Jul 2019
First Registration Date:	08 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$27,662.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jul 2029
PARF Rebate Amount:	\$20,746.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jul 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,961.00
COE Rebate Amount:	\$29,916.00
Total Rebate Amount:	\$50,662.00

The information contained herein is correct as at 03 Jun 2021

OK

Submodel Pricing Information

39.2kWh (A)

View Loan Breakdown

Current price	\$138,888 ▼
? Depreciation	\$13,600 /yr
? Down Payment	\$55,555 (Maximum 60% loan)
? Installment	\$1,185 /mth
COE quota premium	\$58,089 (Category B COE)
? Road tax	\$1,060 /yr
? OMV	\$39,738
? ARF	\$5,000 (After VES & EEAI rebates)
? VES	\$25,000 (Rebate)
? EEAI	\$20,000 (Rebate)
? Total basic cost	\$114,330
? Premium	21%
Previous recorded price	\$140,888
Highest recorded price	\$140,888 (past 6 mths)
Lowest recorded price	\$138,888 (past 6 mths)
» View full price history	