

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21006382/Upa3q2
	8 SHENTON WAY AXA TOWERSING			Date:	07/07/2021
	ATTN:KIAN CHUAN	N		Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SH 6610H	Veh. Inspected	i	SKB 7799S
	Policy No.	P2426680	Coverage (\$)		0.00
	Claim No.	S1M03B7C	Excess (\$)		0.00
	Assign From		Assign Date		03/06/2021
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN QASHQAI (A)	c.c		1197
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	SJNFEAJ11U1698587	Colour		WHITE
	Odometer	85954 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	224/45Z R19	NEXEN		6 mm
	L/H Front Tyre	224/45Z R19	NEXEN		6 mm
	R/H Rear Tyre	224/45Z R19	NEXEN		6 mm
	L/H Rear Tyre	224/45Z R19	NEXEN		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION & N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	02/06/2021	Inspection Dat	e	03/06/2021
	Survey held at	FASTECH AUTO PTE LTD	•		
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		2 Worki	ng Days