(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC4/ASM2/006382/U p3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB7799S

at Workshop m/s ff.

of

Insured: SH 6610H

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: $56k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 461J Vehicle: IN / OUT

Date: Person Contacted: Dayton.

Veh No: SKB7799S Yr Regn: 29/6/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA/

Make: Nissan Qashqai c.c 1197

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 85954 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJNFEAJ11U1698587

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45ZR19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or nexen

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	2/6/21	D.O.I.	3/6/21

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Frt & N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MA 38249 have GIA reject.

14/6/21 L/S $3000 Confirmed with Alex.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS, __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)