

ASS. REC. BY:

REF: CS3/CTI21004156/Gqf3-1

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

04/06/21

From (Person): PAULINE THAM

of CTI

Date/Time: 31/3/2021 10:20 AM

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 1326L

Insured:

GBH 5391Y

at Workshop m/s

Teamwork Garage Pte Ltd

Tel:

68442475

of 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi

Policy No:

DMCVSNW00051542001

Claim No:

SNM21D201788C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/03/2021

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 31-03-21 4.32P.M

Person Contacted:

DARREN

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLS 1326L - X
	GBH 5391Y- NA/CTI21003979/Y DOA:26/03/2021