

(08/11/13) wef

ASS. REC. BY: Farah

REF:

CC4/11121006422/Rigs3

S
9306

COE XPIRY: 2023/1000

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 294Lat Workshop m/s Hin Luanhof 1008, Bukit Merah LN 3 # 01-20

Insured:

111

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

23K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJL 294L

Yr Regn: 2008 1M0V

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Crossroad 1.8 LXA c.c 1799

Colour

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

274394

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RT11008436

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/05/21

D.O.I.

08/06/21

Survey held at

Hin Luanh

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 15K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

934E

Vehicle Details

Vehicle No.:

SJL294L

Vehicle to be Exported:

Yes

Intended Deregistration Date:

30 Jun 2021

Vehicle Make:

HONDA

Vehicle Model:

CROSSROAD 1.8 LX A

Primary Colour:

Black

Manufacturing Year:

2008

Engine No.:

R18A3011467

Chassis No.:

RT11008436

Maximum Power Output:

103.0 kW (138 bhp)

Open Market Value:

\$18,347.00

Original Registration Date:

12 Nov 2008

First Registration Date:

12 Nov 2008

Transfer Count:

1

Actual ARF Paid:

\$18,347.00

Intended PARF Rebate Details

Forfeited

PARF Eligibility:

-

PARF Eligibility Expiry Date:

\$0.00

PARF Rebate Amount:

11 Nov 2023

Intended COE Rebate Details

COE Expiry Date:

B - Car (1601cc & above)

COE Category:

5

COE Period(Years):

\$16,061.00

PQP Paid:

\$7,593.00

COE Rebate Amount:

\$7,593.00

Total Rebate Amount:

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jun 2021

OK

le/Time,

Date/Time

2)

Report
Lump

Honda Crossroad 1.8A LX (COE till 07/2023)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

Price	\$20,800		
Depreciation ?	\$9,710 /yr	Reg Date	06-Aug-2008 (2yrs 1mth 22days COE left)
Mileage	140,000 km (10.9k /yr)	Manufactured ?	2008
Road Tax ?	\$1,271 /yr	Transmission	Auto
Dereg Value ?	\$7,903 as of today (change)	OMV ?	\$17,134
COE ?	\$18,444	ARF ?	\$17,134
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight ?	1,480 kg	No. of Owners ?	5
Type of Vehicle	SUV		

Features

4-cylinders In-line 16-valves Engine. View specs of the Honda Crossroad (2008-2011)