

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH 8921Y

Date: 07/06/2021

Make : HYUNDAI

Insurance: **AIG**

Model : IONIQ(G3)

MVA: **MS. LOKE YY**

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$430.90
10	FRT BUMPER CLIPS		\$2.20	\$22.00
1	FRT BUMPER BRACKET LH			\$28.00
1	FRT FENDER LH			\$588.80
1	FRT FENDER EMBLEM 'BLUE DRIVE' LH			\$26.60
1	FRT WHEEL HUB CAP LH			\$346.40
	SUB TOTAL			\$1,442.70
	LESS 20%			\$288.54
	DISCOUNTED TOTAL			\$1,154.16
	Labour Charge			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$600.00
	TUFF KOTE			\$50.00
	TOTAL LABOUR			\$1,350.00
	ESTIMATE TOTAL			\$2,504.16

DEF
 NEU
 ?
 X R
 NEU
 SCR

500
 40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
 7/6/2021 1615
 PIP
 3 DAY
 CHECK HEMPHOTO
 BY PAINT PHOTO

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Sign