

ASS. REC. BY:

Steve

REF.

CS/CT121906462/ETC

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 6643X

Yr Regn:

31/3/21

Type: M.Cár / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Seltos

c.c 1353

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

2149

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NUMBER 811VLU1121398

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

3/6/21

D.O.I.

7/6/21

Survey held at

cycle &amp; collapse

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Re RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK-190K

Confirm final figure at \$32,487.66, 18 working days

red: 11599.12 26%

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: 18

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Misc. (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Form:

Lump Sum / LBS:



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info	
CHOON GUOBIN, EUGENE (GONG GUOBIN)	Cust No/Name	LCV13996/CHOON GUOBIN, EUGENE (GONG GUOB)
BLK 278B COMPASSVALE BOW	Reg No/Reg Date	SLH6643X / 31/03/202
#11-561	Date In/Mileage	04/06/2021/ 2149
SINGAPORE 542278	Chassis No	MZBER811VLN121398
Contact No Mobile: 81231758	Engine No	G4LDLD035879
	Make/Model	KIA/SELTO 1.4 A SX SR G605
	Colour/Trim	BNB INTELLGENCY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / CocoLu	34135			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000					7	x 640		9600.00
RENEW REAR BUMPER, REAR END PANEL, REAR LAMP HOUSING RH								4480
I TAILGATE, REAR FENDER RH, A-PILLAR RH, REAR FENDER INNER PANEL RH								
REPAIR ROOF PANEL								
E PNT88000								200.00
REMOVE & INSTALL REAR QUATOR GLASS RH								
E PNT88000								640.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS, REAR SEALTS , CARPETS (photo)								
E PNT88000								300.00
REMOVE & INSTALL REAR FENDER INNER TRIMS (photo)								
E PNT88000								320 640.00
REMOVE & INSTALL ROOF LINING (photo)								
E PNT88000								80 100.00
REMOVE & INSTALL PARKING SENSOR								
E PNT88000								300.00
REMOVE & INSTALL TAILGATE GLASS								
M SUNDRY								80.00
APPLY SEALANT FOR TAILGATE GLASS								
M SUNDRY								240.00
APPLY SOLAR FILM FOR TAILGATE GLASS								
M SUNDRY								40.00
C&C LOGO								
M SUNDRY								80 120.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								? 50.00
REAR BUMPER PLATE WITH FRAME								
M SUNDRY								680.00
SUPPLY IN CAR CAMERA REAR MISSING - m/s								
E PNT98000					1/2			4950.00
SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR LAMP HOUSING RH								3300
REAR INNER FENDER RH, TAILGATE, A-PILLAR RH, REAR COMPARTMENT,					6	x 550		
I ROOF LINING								
B WHEELALIGNMENT								120.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the windscreen or other repairs requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
 PANDAN GARDENS CUSTOMER SERVICE CENTRE  
 209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : WP-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
CHOON GUOBIN, EUGENE (GONG GUOBIN) BLK 278B COMPASSVALE BOW #11-561 SINGAPORE 542278 Contact No Mobile: 81231758	Cust No/Name LCV13996/CHOON GUOBIN, EUGENE (GONG GUOBIN) Reg No/Reg Date SLH6643X / 31/03/202 Date In/Mileage 04/06/2021/ 2149 Chassis No MZBER811VLN121398 Engine No G4LDLD035879 Make/Model KIA/SELTOS 1.4 A SX SR G605 Colour/Trim BNB INTELLGENCY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / Cocolu	34135
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
To Conduct Computerize Full Wheel Alignment					
A 90000001					✓ 50.00
CHECK WIRING & ELECTRICAL SYSTEM					
M SUNDRY					30.00
TRANSFER REAR LEFT RIM					
A 10028901					280.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					
USING HI-SCAN PRO TEST					
M SUNDRY					20.00
Sundry					
M SUNDRY					160.00
APPLY SOLAR FILM FOR REAR QUARTER GLASS					20.00
M SUNDRY					
S SPECIALISTJOB					
WO: 1257669 ACCIDENT TOWED FROM JIN KAYU TO CNC PG					
Date 3/6/21(Thur); Time Start 16.05pm, Time End 15.45pm (bill)					
E PNT88000					300.00
REMOVE & INSTALL FRT WINDSCREEN (photo)					
M SUNDRY					80.00
APPLY SEALANT FOR FRT WINDSCREEN					
M SUNDRY					? 500.30
GRACO CAR SEAT DLX 4 IN 1					
M SUNDRY					? 58.36
GRACO BOOSTER SEAT					
M SUNDRY					? 319.00
ERGOBABY BABY CARRIER					
M REAR BUMPER	1.00	249.00	00.00	249.00	
M SKID PLATE-RR BUMPER / CUT	1.00	71.00	00.00	71.00	
M MOULDING ASSY-RR BUMPER, RH / BR	1.00	67.00	00.00	67.00	
M COVER-RR BUMPER SIDE UNDER, RH	1.00	13.00	00.00	13.00	
M LAMP ASSY-REAR R/REFL, RH	1.00	28.00	00.00	28.00	
M BEAM-RR BUMPER	1.00	222.00	00.00	222.00	

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
CHOON GUOBIN, EUGENE (GONG GUOBIN) BLK 278B COMPASSVALE BOW #11-561 SINGAPORE 542278 Contact No Mobile: 81231758	Cust No/Name LCV13996/CHOON GUOBIN, EUGENE (GONG GUOB Reg No/Reg Date SLH6643X / 31/03/202 Date In/Mileage 04/06/2021/ 2149 Chassis No MZBER811VLN121398 Engine No G4LDLD035879 Make/Model KIA/SELTOS 1.4 A SX SR G605 Colour/Trim BNB INTELLGENCY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / CocoLu	34135
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M WIRING HARNESS-RR BUMPER	?	1.00	246.00	00.00	246.00
M BRACKET-RR BUMPER SIDE MTG,RH	GR	1.00	27.00	00.00	27.00
M MOULDING-REAR BUMPER,CTR	GR	1.00	160.00	00.00	160.00
M MOULDING-REAR BUMPER,RH	GR	1.00	125.00	00.00	125.00
M ULTRASONIC SENSOR ASSY-P.A.S	?	4.00	108.00	00.00	432.00
M RETAINER-BUMPER SIDE MTG	nec	8.00	3.00	00.00	24.00
M LAMP ASSY-REAR FOG	?	1.00	86.00	00.00	86.00
M GARNISH-T/GATE	cut	1.00	375.00	00.00	375.00
M ORNAMENT-KIA	nec	1.00	76.00	00.00	76.00
M GARNISH-TAIL GATE,LWR	?	1.00	19.00	00.00	19.00
M STRIP (A)-T/GATE GARNISH	?	1.00	14.00	00.00	14.00
M UNIT ASSY-REAR VIEW CAMERA	ms	1.00	720.00	00.00	720.00
M GLASS ASSY-TAIL GATE	GR	1.00	228.00	00.00	228.00
M GLASS & MOULDING ASSY-QUARTER FIXED,RH	nec	1.00	268.00	00.00	268.00
M MOULDING ASSY-ROOF,RH	?	1.00	16.00	00.00	16.00
M RACK ASSY-ROOF,RH	?	1.00	420.00	00.00	420.00
M EMBLEM-TURBO G.D.I	nec	1.00	11.00	00.00	11.00
M EMBLEM-SELTOS	nec	1.00	25.00	00.00	25.00
M TRIM ASSY-RR TRANSVERSE	?	1.00	36.00	00.00	36.00
M BOARD ASSY-LUGGAGE COVERING	?	1.00	358.00	00.00	358.00
M TRIM ASSY-LUGGAGE SIDE RH	?	1.00	128.00	00.00	128.00
M HEADLINING ASSY	?	1.00	665.00	00.00	665.00
M TRIM ASSY-RR PILLAR RH	?	1.00	47.00	00.00	47.00
M PANEL ASSY-TAIL GATE	00	1.00	976.00	00.00	976.00
M PANEL ASSY-BACK	?	1.00	391.00	00.00	391.00
M PANEL ASSY-REAR FLOOR	?	1.00	707.00	00.00	707.00
M EXTENSION ASSY-QTR OTR RR RH	?	1.00	181.00	00.00	181.00
M PANEL ASSY-QUARTER INNER,RH	00	1.00	808.00	00.00	808.00
M PANEL ASSY-QUARTER OUTER,RH	00	1.00	420.00	00.00	420.00
M GARNISH ASSY-QTR SIDE,RH	?	1.00	50.00	00.00	50.00
M GARNISH ASSY-RR DR SIDE,RH	?	1.00	74.00	00.00	74.00
M MOULDING ASSY-SIDE SILL,RH	GR	1.00	164.00	00.00	164.00
M LAMP ASSY-LUGGAGE COMPARTMENT	?	1.00	12.00	00.00	12.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
CHOON GUOBIN, EUGENE (GONG GUOBIN) BLK 278B COMPASSVALE BOW #11-561 SINGAPORE 542278 Contact No Mobile: 81231758	Cust No/Name LCV13996/CHOON GUOBIN, EUGENE (GONG GUOBIN) Reg No/Reg Date SLH6643X / 31/03/202 Date In/Mileage 04/06/2021/ 2149 Chassis No MZBER811VLN121398 Engine No G4LDLD035879 Make/Model KIA/SELTO 1.4 A SX SR G605 Colour/Trim BNB INTELLGENCY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / CocoLu	34135
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-LICENSE PLATE	?	2.00	16.00	00.00	32.00
M LAMP ASSY-REAR COMB OUTSIDE, RH	BR	1.00	588.00	00.00	588.00
M LAMP ASSY-REAR COMB INSIDE, RH	BR	1.00	432.00	00.00	432.00
M LAMP ASSY-HMS	?	1.00	102.00	00.00	102.00
M BLADE ASSY-WIPER, RR	?	1.00	33.00	00.00	33.00
M ARM & HEAD CAP ASSY-RR WIPER	?	1.00	82.00	00.00	82.00
M MOTOR & LINKAGE ASSY-REAR WPR	?	1.00	430.00	00.00	430.00
M WHEEL ASSY-ALUMINIUM	CAT	1.00	931.00	00.00	931.00
M LIFTER ASSY-TAIL GATE, RH	BT	1.00	78.00	00.00	78.00
M W/STRIP-TAIL GATE OPNG	?	1.00	100.00	00.00	100.00
M TRIM ASSY-TAIL GATE LWR	?	1.00	138.00	00.00	138.00
M LATCH ASSY-TAIL GATE	?	1.00	219.00	00.00	219.00
M BRACKET, IU ADHESIVE	?	1.00	26.00	00.00	26.00
M LIFTER ASSY-TAIL GATE, LH	?	1.00	78.00	00.00	78.00

Estimate

Stork CLKK wil RL  
7/6/21, 5.30pm P/P  
My Bel sy  
18 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

7% GST on 32085.66

Total Payable 34,331.66

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission  
Date of Accident  
Exact Location of Accident  
Additional Location Information  
Country/State of Loss

03/06/2021 17:12 (SGT)  
03/06/2021 13:55 (SGT)  
Jln Kayu, Singapore  
JALAN KAYU ROAD (TOWARDS TPE)  
Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLH6643X

## INSURED/POLICYHOLDER

Is company?  
Name Of Registered Owner  
NRIC No  
Email Address  
Mobile Phone No  
Alternative Phone No

No  
CHOON GUOBIN, EUGENE  
SXXXX363F  
EUGENECHOON@GMAIL.COM  
(Phone) +65-81231758  
+65-81231758

## VEHICLE PARTICULARS

Manufacturer  
Model  
Variant  
Exact purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle?  
Vehicle Category  
Transmission  
CC

Kia  
SELTOS

Private use

No - Claiming third party  
Private car  
Auto  
1353

## INSURANCE COMPANY

Name of Insurance Company  
Type of Coverage  
Fleet Policy  
Policy Number  
Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd.  
Comprehensive  
No  
7210031804

## DRIVER

Name of Driver  
NRIC No

CHOON GUOBIN, EUGENE  
SXXXX363F

Date of Birth  
Location  
Driving Pass  
Driving experience  
Licence Number  
Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance?

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Was notice of intended Prosecution given?  
If yes, against whom?

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number  
Address  
Address complement

12/09/1987  
Indoor  
27/02/2012  
9 YEARS AND 4 MONTHS  
Male  
(Phone) +65-81231758  
+65-81231758  
EUGENECHOON@GMAIL.COM  
BLK 278B COMPASSVALE BOW #11-561

542278  
Yes

No

Collided Into Parked Vehicle  
Clear  
Dry

No  
3  
No  
-  
Yes  
1  
No

No  
No  
-

Yes  
Yes  
No

GBE8683B  
Toyota

Commercial vehicle  
HUANG ZHONGJU (YONG HE FU CONSTRUCTION)  
(Phone) +65-92369438



Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

SJT5264C

Private car

## SKETCH PLAN

### IMPORTANT NOTICE


- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: SLH 6643X

B: GBE 8683B

C: SLT 5264  
SJT 5264C


**Describe Circumstances of the Accident**

My car was parked properly in Loading/Unloading bay per to the guidelines for taking less than 5 min later, the lorry collided on the back of my car and car moved forward onto the pedestrian pathway


red. 11599.12

**Declaration**

We declare the foregoing particulars are true in every respect.

 3/6/2021  
15:54 hr  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel