

ASS. REC. BY:

Steve

CS/AIG 21006466/EVP3

ASSIGNMENT

From:

Date:

Estimated Cost:

TP/VIS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN/OUT

Date: Person Contacted:

Veh No:

SMH 178A

Yr Regn:

26/3/19

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Stinger

c.c

1998

Colour:

Red

A/C: Insured / Std / NI / N

Sp. Reading

30466

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNAE351 AFAK 600622

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brakes: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

6/6/21

D.O.A.

8/6/21

Survey held at

cycle & canopy

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH, Rear RL

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-14SK

Time/Time, File, Ross to?



: Prel. Report



: Final Report

Time/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Insp

(\$



: Weekend

(\$

\$ - RS - \$

Photos

Others

TOTAL

Approved:

Signature / Date:



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4KCLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim HAR HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY PANEL COMPL-COMB LAMP HSG,LH / BR (no price) KS69131J5100				
M SUNDRY PANEL ASSY-QUARTER INNER,LH KS71601J5000				
M SUNDRY CROSSMEMBER COMPL-RR KS55405J5000				
M SUNDRY ARM COMPLETE-RR LWR,RH KS55211J5000				
M SUNDRY BACK ASSY-FR SEAT,LH / BR (no price) KS88300J5470CLL				
E PNT88000 RENEW LHR DOOR , LHR FENDER , LHR WHEELHOUSE , RR BUMPER & RHR DOOR REPAIR RR END PNL , RR CHASSIS & ROOF PNL(RH)	6 X 400			2400 4000.00
E PNT98000 RESpray LHR DOOR , LHR FENDER , LHR WHEELHOUSE , LH ROCKER PNL , BOOTLID , RR END PNL , RR BUMPER , RHR FENDER & RHR DOOR	6 X 480			2880 3500.00
A 54900099 RENEW LH SIDE CURTAIN AIRBAG , LHF SEAT AIRBAG & SENSOR				400 800.00
E PNT88000 REMOVE & REFIT LHR DOOR COMPONENT				120.00
E PNT88000 REMOVE & REFIT RHR DOOR COMPONENT				120.00
M SUNDRY RENEW LHR SPORT RIM & TRANSFER TYRE				30.00
A 13900099 REMOVE & REFIT FUEL TANK ASSY (photo)				400.00
E PNT88000				400.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4KLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
REMOVE & REFIT RR FLOOR BOARD , CARPET , SEAT & TRIM (phib)					200	400.00			
E PNT88000	REMOVE & REFIT ROOF LINING						30.00		
A 54900099	CHECK WIRING ELECTRICAL SYSTEM						120.00		
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					?	1000.00		
E PNT88000	CONDUCT CHASSIS ALIGNMENT USING CELETTE BENCH						120.00		
A WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment (phib)					400	600.00		
A 34900099	RENEW REAR U/CARRIAGE LH					?	600.00		
A 34900099	RENEW REAR U/CARRIAGE					?	1200.00		
A 34900099	REMOVE & REFIT RR X-MEMBER & RR DIFFERENTIAL ASSY						120.00		
E PNT88000	RENEW RHR DOOR GLASS						80.00		
M SUNDRY	SUPPLY RHR DOOR GLASS SOLAR FILM						80.00		
E PNT88000	REMOVE & REFIT REVERSE SENSOR					40	80.00		
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS						80.00		
M SUNDRY	SUPPLY BODY PNL SEALANT						40.00		
M SUNDRY	SUPPLY C&C BADGE						30.00		
M SUNDRY	Sundries								
M	PANEL ASSY-REAR DOOR,RH / 00					1.00	911.00	20.00	728.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4CLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOULDING ASSY-RR DR FRAME,RH	✓ BT nec			1.00	69.00	20.00	55.20
M	GARNISH ASSY-RR DR FRAME RH	✓			1.00	120.00	20.00	96.00
M	W/STRIP ASSY-RR DR BELT O/S RH	✓ BT			1.00	45.00	20.00	36.00
M	GLASS ASSY-REAR DOOR,RH	X			1.00	209.00	20.00	167.20
M	PANEL ASSY-REAR DOOR,LH	✓ DD			1.00	911.00	20.00	728.80
M	MOULDING ASSY-RR DR FRAME,LH	✓ nec			1.00	69.00	20.00	55.20
M	GARNISH ASSY-RR DR FRAME LH	✓			1.00	120.00	20.00	96.00
M	W/STRIP ASSY-RR DR BELT O/S LH	✓			1.00	45.00	20.00	36.00
M	W/STRIP ASSY-RR DR SIDE LH	✓			1.00	91.00	20.00	72.80
M	W/STRIP-RR DR BODY SIDE LH	✓			1.00	91.00	20.00	72.80
M	PAD-FR DR O/S HDL HINGE,LH	✓ (Rear LH) nec			1.00	5.00	20.00	4.00
M	HANDLE-REAR DOOR OUTSIDE,LH	✓ BR			1.00	31.00	20.00	24.80
M	COVER-RR DR O/S HDL,LH	✓ MIS			1.00	17.00	20.00	13.60
M	PAD-DOOR O/S HANDLE REAR,LH	✓ MIS			1.00	5.00	20.00	4.00
M	STRIKER ASSY-DR	✓			1.00	23.00	20.00	18.40
M	LATCH ASSY-REAR DOOR,LH	✓			1.00	280.00	20.00	224.00
M	COVER-RR BUMPER	✓ BR			1.00	639.00	20.00	511.20
M	BRACKET-RR BUMPER RAIL LWR,LH	✓ BR			1.00	29.00	20.00	23.20
M	BRACKET-RR BUMPER RAIL LWR,RH	✓			1.00	29.00	20.00	23.20
M	COVER-RR BUMPER LWR	✓ CUT			1.00	342.00	20.00	273.60
M	LAMP ASSY-REAR R/REFL,LH	✓ BR			1.00	29.00	20.00	23.20
M	LAMP ASSY-REAR R/REFL,RH	X			1.00	29.00	20.00	23.20
M	TRIM ASSY-TAIL,RH	✓			1.00	216.00	20.00	172.80
M	EXTN WIRING ASSY-BWS	✓			1.00	201.00	20.00	160.80
M	RETAINER	✓ nec			6.00	2.00	20.00	9.60
M	BEAM-RR BUMPER	X			1.00	263.00	20.00	210.40
M	STAY-RR BUMPER LH	X			1.00	85.00	20.00	68.00
M	STAY-RR BUMPER RH	X			1.00	85.00	20.00	68.00
M	BRACKET-RR BUMPER,UPR	X			1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM LWR,CTR	X			1.00	6.00	20.00	4.80
M	BRACKET-RR BUMPER,LWR	X			1.00	5.00	20.00	4.00
M	ANTENNA ASSY-SMARTKEY	X			1.00	79.00	20.00	63.20
M	BRACKET ASSY-RR BUMPER SIDE,LH	✓ BR			1.00	64.00	20.00	51.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
ATG BUILDING
SINGAPORE 079120
Contact No 64191000

Owner Name & Vehicle Info


Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)
Reg No/Reg Date SMH178A / 26/03/201
Date In/Mileage / 36466
Chassis No KNAE351AMK6060620
Engine No G4KLKH020362
Make/Model KIA/STINGER 2.0 A GAA4
Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET ASSY-RR BUMPER SIDE,RH	X			1.00	64.00	20.00	51.20
M	ULTRASONIC SENSOR ASSY-BWS	?			2.00	189.00	20.00	302.40
M	LAMP ASSY-SIDE REFLEX REFLECTO	/ MIS			1.00	35.00	20.00	28.00
M	LAMP ASSY-REAR COMBINATION,CTR	X			1.00	1480.00	20.00	1184.00
M	LAMP ASSY-REAR COMB OUTSIDE,LH	/ CUT			1.00	908.00	20.00	726.40
M	LAMP ASSY-REAR COMB OUTSIDE,RH	X			1.00	908.00	20.00	726.40
M	EMBLEM-STINGER	/ NPC			1.00	68.00	20.00	54.40
M	PANEL ASSY-QUARTER OUTER,LH	/ DD			1.00	1955.00	20.00	1564.00
M	PANEL ASSY-FULL FILLER DOOR	/ MIS			1.00	53.00	20.00	42.40
M	HOUSING-FUEL FILLER DR	/ BR			1.00	47.00	20.00	37.60
M	OPENER ASSY-FUEL FILLER DR	/ BR			1.00	74.00	20.00	59.20
M	GUARD-REAR WHEEL,LH	/ CRU			1.00	159.00	20.00	127.20
M	GARNISH ASSY-C.PILLAR,LH	/ ?			1.00	183.00	20.00	146.40
M	GARNISH ASSY-C.PILLAR,RH	/ ?			1.00	183.00	20.00	146.40
M	FILLER NECK & HOSE ASSY	/ BR			1.00	336.00	20.00	268.80
M	FILM-RR DR ANTI CHIPPING,LH	/ nec			1.00	15.00	20.00	12.00
M	FILM-RR DR ANTI CHIPPING,RH	/ nec			1.00	15.00	20.00	12.00
M	FILM-ANTI CHIPPG LH	/ nec			1.00	23.00	20.00	18.40
M	FILM-ANTI CHIPPG RH	/ nec			1.00	23.00	20.00	18.40
M	BAR ASSY-RR STABILIZER	/ ?			1.00	175.00	20.00	140.00
M	LINK ASSY-REAR STABILIZER,LH	/ ?			1.00	83.00	20.00	66.40
M	LINK ASSY-REAR STABILIZER,RH	/ X			1.00	83.00	20.00	66.40
M	RR ARM ASSY-RR UPR LH	/ ?			1.00	118.00	20.00	94.40
M	RR ARM ASSY-RR UPR RH	/ X			1.00	118.00	20.00	94.40
M	ARM COMPLETE-RR UPR FRT	/ ?			1.00	118.00	20.00	94.40
M	ARM ASSY-RR ASSIST,LH	/ ?			1.00	162.00	20.00	129.60
M	ARM ASSY-RR ASSIST,RH	/ X			1.00	162.00	20.00	129.60
M	ARM COMPLETE-RR LWR,LH	/ ?			1.00	164.00	20.00	131.20
M	ARM ASSY-RR TRAILING ARM,LH	/ ?			1.00	156.00	20.00	124.80
M	ARM ASSY-RR TRAILING ARM,RH	/ X			1.00	156.00	20.00	124.80
M	BAR ASSY-STIFFENER	/ ?			1.00	120.00	20.00	96.00
M	STAY	/ ?			2.00	96.00	20.00	153.60
M	BAR ASSY-STIFFENER	/ ?			1.00	120.00	20.00	96.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4CLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M CARRIER ASSY-REAR AXLE, RH	X	1.00	636.00	20.00	508.80
M CARRIER ASSY-REAR AXLE, LH	X	1.00	636.00	20.00	508.80
M HUB ASSY-FR WHEEL	X	1.00	520.00	20.00	416.00
M CAP	X	1.00	9.00	20.00	7.20
M INSULATOR-STRUT	?	2.00	116.00	20.00	185.60
M PAD-REAR SPRING, UPR	?	1.00	20.00	20.00	16.00
M PAD-REAR SPRING, LWR	?	1.00	40.00	20.00	32.00
M SHOCK ABSORBER ASSY-REAR	?	1.00	215.00	20.00	172.00
M CARRIER ASSY-DIFFERENTIAL	?	1.00	2506.00	20.00	2004.80
M WHEEL ASSY-ALUMINIUM LHR	CUT	1.00	1054.00	20.00	843.20
M VALVE-TPMS	RPC	1.00	137.00	20.00	109.60
M HEADLINING ASSY	CRU	1.00	2383.00	20.00	1906.40
M CURTAIN AIR BAG MODULE, LH	BR	1.00	1265.00	20.00	1012.00
M SENSOR ASSY-PRESS TYPE CRASH	RPC	1.00	115.00	20.00	92.00
M SENSOR ASSY-A TYPE CRASH	RPC	2.00	96.00	20.00	153.60
M S/BELT ASSY-FR LH	Jammed	1.00	420.00	20.00	336.00
M S/BELT ASSY-FR RH	Jammed	1.00	420.00	20.00	336.00
M SEAT BELT PRETENSIONER, LH	RPC	1.00	194.00	20.00	155.20
M SEAT BELT PRETENSIONER, RH	RPC	1.00	194.00	20.00	155.20
M ADJUSTER ASSY-HEIGHT	?	2.00	35.00	20.00	56.00
M BUCKLE ASSY-FR S/BELT, LH	?	1.00	134.00	20.00	107.20
M S/BELT ASSY-RR, LH	Jammed	1.00	398.00	20.00	318.40
M S/BELT ASSY-RR, RH	Jammed	1.00	398.00	20.00	318.40
M S/BELT ASSY-RR, CTR	X	1.00	177.00	20.00	141.60

SURVEYOR NAME: Steve CLKK 8/6/21, 11:00am

SURVEYOR SIGNATURE: DD-NY AL

DATE: EXPR-7

REMARKS: PIP, My Bel sy

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

14 dys

7% GST on 35037.20

Nett 35,037.20

2452.60

Total Payable 37,489.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/06/2021 12:11 (SGT)
Date of Accident	06/06/2021 17:40 (SGT)
Exact Location of Accident	Sengkang W Way, Singapore
Additional Location Information	SENGKANG WEST WAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMH178A

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM SI PENG ANTHONY
NRIC No	SXXXX062B
Email Address	ANTHONY.LIMSP@GMAIL.COM
Mobile Phone No	(Phone) +65-96673936
Alternative Phone No	+65-96673936

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Stinger
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900077935-01
Cover Note Number	-

DRIVER

Name of Driver	LIM SI PENG ANTHONY
NRIC No	SXXXX062B

Date Of Birth	17/06/1991
Occupation	Indoor
Date Of Driving Pass	10/11/2010
Driving experience	10 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96673936
Alt. Phone Number	+65-96673936
Email Address	ANTHONY.LIMSP@GMAIL.COM
Address	16 SUNRISE AVENUE
Address complement	-
Postcode	806678
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	NG XIN HUI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT
COLLISION-HEAD TO SIDE

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	MEMORY CARD WITH TRAFFIC POLICE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY: 11

Vehicle Registration Number	SBS5022E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	THEVENTHARAN D MURUGESU
Contact Number	(Phone) +65-82626084
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	SBS BUS NO.86
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS:

INJURED 1

Name of injured person	PEDESTRIAN
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	No
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
06/06/2021 (17:40)
Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

[Signature]
Witnessed by Reporting Centre
Personnel

Sketch Plan




Describe Circumstances of the Accident


Refer to attachment

Declaration

We declare the foregoing particulars are true in every respect.

 06/06/2021 (17:40)
Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20210606/7026

1 of 4

Report No. T/20210606/7026

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
06/06/2021 23:28

Vide Report No.:
F/20210606/0212

Station Diary No.:

Informant's Particulars

Name of Informant:
LIM SI PENG ANTHONY

Address:
16 SUNRISE AVENUE SINGAPORE 806678

ID Type / ID No.:
NRIC NO / S95062B

Contact No.:
Home/Office: Mobile: 96673936

Nationality:
SINGAPORE CITIZEN

Email:
ANTHONY.LIMSP@GMAIL.COM

Sex: Male Age: 29 Date of Birth: 17/06/1991

Type of Informant:
Driver

Race:
Chinese

Language:
English

Institution / School Name:

Occupation:
Engineer Programmer

Driving Licence Information:
Class:

Date of Expiry:

General Information of the Accident

Type of Accident: Injury Attended by Police

Drink Drive:
No

Date/Time of Accident:
06/06/2021 17:40

Type of Location:
X-Junction

Location:

SENGKANG WEST WAY

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
Two Way

Traffic Control:
Traffic Light - Working

Traffic Volume:
Moderate

Type of Collision:
Between Moving Vehicles - Side Swipe - Opposite Direction

Anyone conveyed by ambulance:
Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SMH178A	Car	KIA	STINGER 2.0A 2WD SUNROOF	Red		0
	SBS Bus No. 86					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20210606/7026

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T/20210606/7026

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMH178A	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900077935-01	26/03/2021	25/03/2022

Details of Person Involved				
Any Pedestrian Involved: Yes				
No. of Pedestrians Injured: 2		Use of Pedestrian Crossing: Used		
Passenger				
Name	NG XIN HUI		ID No.	NIL
Related Vehicle	SMH178A (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	Slight
Driver				
Name	LIM SI PENG ANTHONY		ID No.	S 062B
Related Vehicle	SMH178A (Car)		Contact No.	96673936
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL
Driver				
Name	THEVENTHARAN D MURUGESU		ID No.	G 358T
Related Vehicle	(SBS Bus No. 86)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL



SINGAPORE POLICE FORCE



T/20210606/7026

3 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20210606/7026

CONTINUATION OF REPORT

Pedestrian				
Name	Unknown Pedestrian		ID No.	NIL
Related Vehicle	NIL		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	Slight
Pedestrian				
Name	Unknown Pedestrian		ID No.	NIL
Related Vehicle	NIL		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	Slight

Brief Details.

Incident happen at Jalan kayu, sengkang West way cross junction.

I was driving a red car at Jalan kayu road beside ju eng home traffic light, about to make a right turn, it was green light, I check on the right side for Pedestrian and saw there was people crossing, so I waited for the path to be clear, when I accelerate my car to move forward I notice the bus was still at a far distance, so I accelerate to the cleared path to make the right turn into sengkang west way, the next thing I notice the bus was moving very fast heading towards my direction, and in a split second the bus ramp into the rear of my car, I felt my car spinning. And I stop everything. I turn left to check if my wife is ok, and notice my cars airbag was activated on the left side. Next I went down to see if everything is OK, but I was shocked to see a man lying at the side of the curb at sengkang West way roadside, his wife and 2 daughters were with him, and later on many pedestrian came to help out. One of the passerby came to help out and called 995. After which the ambulance and traffic police came to assist on this accident.

I have photos of my car's condition, and video of the incident happen, capture by my car dashcam, my car memory card was taken away by a traffic police officer after that.



**SINGAPORE
POLICE FORCE**



T/20210606/7026

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20210606/7026

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
ABDUL MUHAIMIN BIN HUSSAIN
Contact No.: 65476090

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
06/06/2021 23:28

Classification Of Case:

CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Si Peng Anthony (Lin Sipeng)
 Period of Insurance : 26 Mar 2021 To 25 Mar 2022
 Engine No. : G4KLKH020362
 Chassis No. : KNAE351AMK6060620

Vehicle No. : SMH178A
 Policy No. : 1900077935-01
 Endorsement No. :
 Issued Date : 19 Feb 2021

ABOUT THE COVER

Make/Model : KIA Stinger 2.0
 Engine Capacity/Tonnage : 1,998.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2019
 Insuring with COE/PARF : Yes

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Si Peng Anthony (Lin Sipeng) - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504624201

FULCOKICP2 - BO

22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature