



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM21006480/Ags3q2 Date: 19/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 5050X	Veh. Inspected	SMV 6314K
	Policy No.	GA572887	Coverage (\$)	0.00
	Claim No.	S1M03BC9	Excess (\$)	0.00
	Assign From		Assign Date	07/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C200 AMG	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDD2053422F358762	Colour	BLACK
	Odometer	72903 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/06/2021	Inspection Date	16/06/2021
	Survey held at	NEW ZEN WERKZ PTE LTD 3 KAKI BUKIT ROAD 1, #03-04, SINGAPORE 415935		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	