

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                                                                                |                                                                                   |                            |            |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|----------------------------|------------|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                                                                                                                               |                                                                                   | Ref: CS3/AIG21006504/R1qf3 |            |  |
| 78 SHENTON WAY #09-16                                                                                                                                                                                                                            |                                                                                   | Date: 08/06/2021           |            |  |
| AIG BUILDING                                                                                                                                                                                                                                     |                                                                                   |                            |            |  |
| SINGAPORE 079120                                                                                                                                                                                                                                 |                                                                                   | Code: AIG                  |            |  |
| 1. Policy Particulars :- (THIRD PARTY CLAIM)                                                                                                                                                                                                     |                                                                                   |                            |            |  |
| Insured Veh.                                                                                                                                                                                                                                     | GBF 9690T                                                                         | Veh. Inspected             | SKG 7455H  |  |
| Policy No.                                                                                                                                                                                                                                       | 7210011263                                                                        | Coverage (\$)              | 0.00       |  |
| Claim No.                                                                                                                                                                                                                                        | 8321575212SG                                                                      | Excess (\$)                | 0.00       |  |
| Assign From                                                                                                                                                                                                                                      | DIVYASHNI SUBRAMANIAM                                                             | Assign Date                | 08/06/2021 |  |
| 2. Vehicle Particulars & Condition                                                                                                                                                                                                               |                                                                                   |                            |            |  |
| Make & Model                                                                                                                                                                                                                                     | c.c                                                                               |                            | 0          |  |
| Engine No.                                                                                                                                                                                                                                       | HIDDEN                                                                            | Year of Reg.               |            |  |
| Chassis No.                                                                                                                                                                                                                                      | Colour                                                                            |                            |            |  |
| Odometer                                                                                                                                                                                                                                         | -                                                                                 | Steering                   |            |  |
| Brakes                                                                                                                                                                                                                                           | Modification                                                                      |                            |            |  |
| General                                                                                                                                                                                                                                          |                                                                                   |                            |            |  |
| 3. Conditions of Tyres                                                                                                                                                                                                                           |                                                                                   |                            |            |  |
|                                                                                                                                                                                                                                                  | Size                                                                              | Make                       | Balance    |  |
| R/H Front Tyre                                                                                                                                                                                                                                   |                                                                                   |                            | mm         |  |
| L/H Front Tyre                                                                                                                                                                                                                                   |                                                                                   |                            | mm         |  |
| R/H Rear Tyre                                                                                                                                                                                                                                    |                                                                                   |                            | mm         |  |
| L/H Rear Tyre                                                                                                                                                                                                                                    |                                                                                   |                            | mm         |  |
| 4. Description of Damages                                                                                                                                                                                                                        |                                                                                   |                            |            |  |
|                                                                                                                                                                                                                                                  |                                                                                   |                            |            |  |
| 5. General Information                                                                                                                                                                                                                           |                                                                                   |                            |            |  |
| Accident Date                                                                                                                                                                                                                                    | 07/06/2021                                                                        | Inspection Date            | 08/06/2021 |  |
| Survey held at                                                                                                                                                                                                                                   | DAS AUTO & AIRCON SERVICES<br>BLK 9 PIONEER ROAD NORTH<br>#01-58 SINGAPORE 628461 |                            |            |  |
| 5a. Remarks                                                                                                                                                                                                                                      |                                                                                   |                            |            |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                                                                                   |                            |            |  |