



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM21006508/Bqce2 Date: 28/07/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJN 6182B	Veh. Inspected	SMW 9745A	
Policy No.	P2353908	Coverage (\$)	0.00	
Claim No.	S1M03AY0	Excess (\$)	0.00	
Assign From	KHONG LYNN	Assign Date	08/06/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FIT	c.c	1317	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GK31351205	Colour	BLUE	
Odometer	27045 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/05/2021	Inspection Date	09/06/2021	
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	