

REPAIR ESTIMATE

MVA: MS. LOKE YY

- / CRK
- / NEC
- / SCR
- ?
- XSUL
- XSUL
- / DEF
- XSUL
- ?

NA2 LKK
7/16/2021 1530
LJ
2DAYS
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4086719 JC NO.: 305472

CUSTOMER	COMFORT TRANSPORTATION PTE LTD	REGN NO.: SHA2927M	MILEAGE
MR/MS	7010045	MAKE: TOYOTA	FUEL
CUSTOMER NO.	383 SIN MING DRIVE	MODEL	E.....1/2.....
ADDRESS	Singapore SINGAPORE 575717	PRIUS HYBRID(G4)	DATE/TIME IN 04.06.2021 11
TEL. (R)	65508755	YR OF MANU	TARGET DATE
(P)	(O)	01.04.2019	
DISCOUNT CARD NO.		CHASSIS CODE	COMPLETION DATE/TIM
		JTDKB3FU703079781	


Accident Date: 04.06.2021
NATURE: 3P 04.06.2021

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION

SHA2927M YY

SHA2927M



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Name:
I/C No.:
Vehicle No.:

Exit Pass

Vehicle No.:

Name of Service Advisor Signature/Date

Name of Service Advisor Date

To be returned to Service Reception upon collection

To be kept by Security Guard