

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/HS/TP RES/OD RES/EVA/INV/INV

To inspect Vehicle No: WP0ZZZ98ZLS220111

at Workshop no's

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Lanterns

Veh No:

220111

Yr Regn:

1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Porsche 718 Boxster

Colour:

M. Grey

Sp. Reading

Eng/No:

C/No:

WPO 7779 8 ZLS 220111

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35 ZR20

R:

265/35 ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/1

D.O.I.

27/5/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front and N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Battery flat (veh imported from England)

The Surveyor's report is for custom used and not for claims, so no GIA report.

They will prepare cheque when report is ready.

Date/Time, File Pass to?



: Prel. Report

1) 9/6 TYPIST



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

67x15=1005

170+1005

50

43

80

1348

Report Format: TP

Lump Sum / I.B.I: (\$ 66,763.81