

Date/Time: 07.06.2021 09:25

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4086736

JC NO.: 305472203

CUSTOMER
NAME
COMFORT TRANSPORTATION PTE LTD
7010045
CUSTOMER NO.
383 SIN MING DRIVE
ADDRESS
Singapore SINGAPORE 575717
65508755 (O)
(R)
(P)


REGN NO.: SHD3153G	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 04.06.2021 14:00
YR OF MANU. 14.04.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU087671	COMPLETION DATE/TIME:

QUANTITY CARD NO.

JOB DESCRIPTION

Accident Date: 04.06.2021
NATURE: 3P 04.06.2021

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

Vehicle No.: SHD3153G JU NTUC VAC

Vehicle No.: SHD3153G

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard