

NOTE - (CLPUM)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 07.06.2021
Time: 09:30:21
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305472203
REGN NO : SHD3153G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.04.2016
DATE/TIME IN : 04.06.2021 14:00
ACCIDENT DATE : 04.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	XR
0002 04-01-0103-0739-G ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	?
0003 04-01-0103-0740-G BEAM-RR BUMPER#	1	428.40	20.00	342.72	?
0004 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	252.00	20.00	201.60	X SVL
0005 04-01-0103-0738-G COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	?
0006 04-01-0103-1150-A PROTECTOR MAT	1 N	50.00	2.00-	50.00	✓ NPL

SUB-TOTAL : 1,757.12

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 680.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.06.2021

Time: 09:30:21

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305472203
REGN NO : SHD3153G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.04.2016
DATE/TIME IN : 04.06.2021 14:0
ACCIDENT DATE : 04.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,437.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NAZ UKK
7/6/2021 1545
LIS
2 DAYS
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: