

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	GREAT AMERICAI	N INSURANCE COMPANY		Ref:	CS3/GAI21005136/R1tf3e2-1	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	AL TOWER		Date:	14/06/2021	
				Code:	GAI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBD 6640T	Veh. Inspected		YP 384L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CLMOMVC000003959	Excess (\$)		0.00	
	Assign From	ELIZABETH CHEW	Assign Date		09/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	ISUZU NNR85UH4A	c.c		2999	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JAANNR85HF7100229	Colour		BLUE	
	Odometer	73350 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/85 R16	BRIDGESTONE		7 mm	
	L/H Front Tyre	195/85 R16	BRIDGESTONE		7 mm	
	R/H Rear Tyre	185/80 R15 (D)	BRIDGESTONE		7/7 mm	
	L/H Rear Tyre	185/80 R15 (D)	BRIDGESTONE		7/7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/02/2021	Inspection Dat	е	27/04/2021	
	Survey held at	WILLY MOTOR COMPANY				
		27A JURONG PORT ROAD #01-32				
	SINGAPORE 619101					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	•					