

ASS. REC. BY:

REF: CS/

MSG/21008544/Kqf3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBK 9135D

at Workshop m/s Cheng Hoe

Insured: YN 3626E

Policy No. 28653857MKC

Claims No. 636437

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

22/6/2021 @ 12.33pm Revise to MSIG via Merimen.

29/06/21 @ 5.09pm Email Douglas, seek mandate approval.

22/07/21 @ 10.47am Kumar approved mandate at \$3376.95 by email.

Kenneth confirmed final fig \$3376.95, 4 days (Red \$840.02, 20%)

Veh No: GBK 9135D Yr Regn: 01, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Dyno C.C. 2982Colour: White A/C: Insured / Std / NI / NASp. Reading: 1689 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: JTFA735Y50K216031

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: MT / S/Rlm / STD A/Rlm orTyre Size: F: 195/75R15R: 155R12x8101

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 4/6/21

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 27/07 Typist

Date/Time, File Return to?

2)

Report Format: MER-TP

Lump Sum / I.B.I: (\$ 3376.95)

☐ : Prell. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

S + RS. \$

Parking

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Cheng Hoe Motor Pte Ltd

Bkk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBK 9135D
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Not Authorized

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 04/06/2021

TP Veh Reg No: YN3626E

*Repair by paint
4 days*

Estimate No: ES2190553/YISHUN

Date: 18 Jun 2021

Policy No: DMCVSNA00007812100

Veh Reg No: GBK9135D

Make/Model: TOYOTA TOYOTA
DYNA 150 5MT

Chassis No: JTFAT35Y50K216031

Engine No: 1KDB064725

Reg. Date: 15/01/2021

Estimate Repair Cost to Vehicle No :GBK9135D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT LH DOOR	1,794.20	1 PC	<i>B</i> 1,794.20	✓
2 FRONT LH DOOR TOP HINGE	110.00	1 PC	<i>n</i> 110.00	X
3 FRONT LH CORNAL GARNISH	336.30	1 PC	336.30	?
4 HEADLAMP LH	928.70	1 PC	<i>cu</i> 928.70	✓
5 FRONT LH SIDE MIRROR	600.10	1 PC	<i>roll in</i> 600.10	✓
			3,769.30	
		Less 25%	942.33	2,826.98
Special Net				
6 FRONT LH DOOR COY STICKER	20.00	1 PC	<i>me</i> 20.00	✓
7 FRONT LH DOOR ADVERTISEMENT STICKER	80.00	1 PC	<i>me</i> 80.00	<i>60.00</i>
			100.00	100.00
Labour				
8 REMOVE & REFIX FRT LH DOOR TRANSFER DOOR LOCK ASSY, INNER TRIM BOARD, RUBBER, REMOVE & REFIX FRT LH SIDE MIRROR & CORNAL GARNISH, KNOCK & REPAIR FRT LH W/SCREEN PILLAR & REALIGN CABIN POSITION	700.00	1 LA	700.00	<i>400</i>
9 REMOVE & REFIX FRT LH DOOR GLASS	60.00	1 LA	60.00	✓
10 PUTTY & RESPRAY ON FRT LH CORNAL GARNISH, FRT LH DOOR, PILLAR	500.00	1 LA	500.00	<i>450</i>
11 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,290.00	1,290.00
			Total	S\$ 4,216.98
			Add GST @ 7%	295.19
			Total Amount Payable	S\$ 4,512.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/06/2021 18:09 (SGT)
Date of Accident 04/06/2021 10:37 (SGT)
Exact Location of Accident Singapore
Additional Location Information 8A ADMIRALTY ST. #06-01
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBK9135D

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TUAN GOU PTE LTD
Company Reg No 2XXXXX312D
Email Address huangcheng318@gmail.com
Mobile Phone No (Phone) +65-87861165
Alternative Phone No (Office) +65-66849555

VEHICLE PARTICULARS

Manufacturer Toyota
Model Dyna
Variant
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 2982


INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMCVSNA00007812100
Cover Note Number 15/01/21 - 14/01/22

DRIVER

Name of Driver WANG BAOQIAN
Passport No/FIN GXXXX683N

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was parked outside the above unit. I was packing my goods preparing to load into my vehicle when suddenly I heard sound and realized my vehicle was being dragged by vehicle B who passed by thus causing damage to my vehicle left portion.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

REG. NO.
201701312D
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()