

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	16:57hrs
ACCIDENT DATE	03-Jun-21
BUS CAPTAIN NAME	RAGHU S/O KUPPEN
THIRD PARTY CLAIM AGAINST	AIG Asia Pacific Insurance

BUS REGISTRATION NUMBER	SG7005D
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	OS BATTERY COMPARTMENT DOOR MTG <i>repair</i>	1	\$840.00
2	OS REAR LAST COMPARTMENT <i>repair</i>	1	\$840.00
3	ADVERTISEMENT STICKER <i>NE /</i>		<i>200</i> \$250.00
4			
5			
6			
7			
8			
		7% GST	\$135.10
		PARTS TOTAL COST	\$2,065.10

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO DISMANTLE & REPLACE :-		
• OS BATTERY COMPARTMENT DOOR MTG	320	\$1,950.00
• OS REAR LAST COMPARTMENT DOOR MTG		
•		
•		
SPRAY PAINTING :-		
• OS BATTERY COMPARTMENT DOOR MTG	640	\$1,280.00
• OS REAR LAST COMPARTMENT DOOR MTG		
•		
•		
CONTRACTOR'S COST :		
TO REPLACE ADVERTISEMENT STICKER	100	\$150.00
		7% GST
		\$236.60
		LABOUR TOTAL COST
		\$3,616.60

SPRAY PAINTING \$640 PER PANEL
LABOUR CHARGES \$650 PER DAY

ESTIMATED ACCIDENT REPAIR COST



SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	
-------------------	--

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	10-Jun-2021
		DATE & TIME SURVEY	10-Jun-2021
		DATE OUT	
		TOTAL NUMBER OF DAYS	
BUS TYPE (SD / DD)	DD		
LOSS OF USE COST			\$1,600.00

SUMMARY	
SECTION NO.	COST
1	\$2,065.10
2	\$3,616.60
3	-
4	\$1,600.00
TOTAL	\$7,281.70

Rahul
Hp 90010568
3 days
10/06/21 @ 1420
Resny after repair

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: