SP0U216G0006 / PROGRESSIVE CAR CARE PTE LTD ENTRY DATE & TIME: 16/06/2021 17:05 (SGT) SUBMITTED BY: Ng Pei Wen VERSION: 1 (16/06/2021 17:05 (SGT))

# **SINGAPORE ACCIDENT STATEMENT**

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission	16/06/2021 17:05 (SGT)
Date of Accident	08/06/2021 13:54 (SGT)
Exact Location of Accident	Tampines St. 11, Singapore
Additional Location Information	OPEN SPACE CARPARK
Country/State of Loss	Singapore

# **DETAILS OF OWN VEHICLE**

Mitsuhishi

Vehicle Registration Number	SMW5391M

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN WOEI LIN
NRIC No	S8706666E
Email Address	FLARIA.TAN@GMAIL.COM
Mobile Phone No	(Phone) +65-85225738
Alternative Phone No	+65-85225738

# VEHICLE PARTICULARS

Manufacturer

Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to	No. Donastino cale
your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	1998

## INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070164719
Cover Note Number	-

# DRIVER

Name of Driver	TAN SIEW KIAH
NRIC No	S1334159A

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	02/08/1958 Indoor 10/11/1975 45 YEARS AND 7 MONTHS Male (Phone) +65-94246158 - FLARIA.TAN@GMAIL.COM BLK 886A TAMPINES STREET 83 #02-55 - 521886 No Parent No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collided into Parked Vehicle Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?  Number of vehicles involved in the accident  Was anybody injured in the Accident?  Was any injured conveyed to hospital by ambulance?  Was any other material or property damaged?  Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  PASSENGER 1	No 2 No - Yes 2
Name Gender	GRANDSON Male
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?  CIRCUMSTANCES OF ACCIDENT	No No -
REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR	CARE PTE LTD TEL 6741 5336
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer Vehicle Model	

Vehicle Variant
Vehicle Colour

Vehicle Category	Private car
Name of Driver	_
Contact Number	_
Address	_
Address complement	_
Postcode	_
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	-
No. Of Fassenger (including Driver)	-

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A-SMW 5391M B-SK753157

- 0	Describe Circumstances of the Accident
[	I want to tampines street II to pack lunch on stune 2001 afternoon around
- 1	2 plus. Are i parked adjucent opposite of the car, skt 5315Z.
1	After packing of runch, I drove my car straight to the opposite
1	empty lot beside the car, SKT 53152 as it was more shady.
1	When I drove slowly to the opposite impty car lot, I accidentally
1	Sciratched to outs the car skt 53152 on to its right front which are
1	upon is the stroyed impact; immediately brake and hereice back to mymn
	Original Car lot. No one was original from this accordate
	I came down the vehicle to ox: assess the dear damages at both vehicles
	and Dailed for the owner of OCT 50152. See to After taking or
	look of both vehides, noted that both have light state ( Scructes.
	I whatel for 5 mins before morning to the multi-story carporal because
	I did not want to leave my grand son under the hot loss Sun.
	iffer parking into the multi story carpork, i returned to the second
	State the nearby sheltered area to what for the owner again for
8	15-20 mas. II dod not managed, to see the owner coming
	back to the car and i also did not have pen and paper at
	the time, & Assessing that the damages on SKT 53152 was not
to ten	report i to left the Carpark to tend to my grandson.
details	truft of the couper to the grantes
demi	I returned to the Carpall on 15 Jun 2021 to buy tunch an healfast
	and sow the car SKT 53157 again. I had placed a note with
	my contact details and my brief details of the allident on the
	owner's car. I did not received any contact from the owner
	however I i received a lefter from LKK Auto consultant PTE CTD #E to
	my dayanter's Ex (car owner) address.
3	
i i	
j.	
	Declaration
	We declare the foregoing particulars are true in every respect.
	If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim
	must be niade within the stipulated timeframe from the day of occurrence. Kindly check with your insurer for more details.
	Will the state of
	Man 99
	Policyholder's Signature Date & Driver's Signature (K driver is not the policyholder) / Date Witnessed by Reporting Centre
	Time & Time Personnel
	Taper
	14 M
	1014121















