



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:YVONNE

Ref: CC4/ASM21006554/Ags3q2
Date: 17/09/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3110R	Veh. Inspected	SMD 8340R
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S1M03BBT	Excess (\$)	0.00
Assign From		Assign Date	09/06/2021

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAF3416MK5011560	Colour	BLACK
Odometer	53114 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/06/2021	Inspection Date	09/06/2021
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **11 Working Days**